





report date: 2024-03-28

General information

Make	MAZDA
Model	CX-5 D SE-L
Colour	Black
Year of manufacture	2013
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	380 Nm at 2.600 rpm
Engine capacity	2.191 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	54.3 mpg
CO2 emission	136 g/km
CO2 label	Е



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-05-23

Pictures 69

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-07-04
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #11		2023-07-03 14:15
MOT test	number	897256965539
Result		✓ Passed
Next expi	ry date	2024-07-04
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #10		2023-06-28 14:33
MOT test	number	930264219930
Result		× Failed
Advice	Front Suspension component corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Fail Of	ffside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 3/12



report date: 2024-03-28

617106032123

 MOT #9
 2022-07-05 13:25

 MOT test number
 420655170121

Result ✓ Passed

Advice Nearside Front Sus

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4

(a) (i))

Advice Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

MOT #8 2022-07-04 11:06

MOT test number 265622563764

Result X Failed

Fail

Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice

MOT test number

Rear Child Seat fitted not allowing full inspection of adult belt

MOT #7 2021-06-29 12:12

MOT test number 793001196965

Result ✓ Passed

MOT #6 2021-03-19 14:53

MOT test number 191520176444

Advice Front Brake pad(s) wearing thin All front pads nearing wear limit. (1.1.13 (a) (ii))

MOT #5 2020-03-16 14:47

MOT test number 371642895331

Result ✓ Passed

MOT #4 2019-03-30 09:52

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #3	2018-03-22 09:06
MOT test number	341239925567
Result	✓ Passed
MOT #2	2017-03-31 15:06
MOT test number	881297058158
Result	✓ Passed
Advice Both front tyres wearing on inner edges.	

MOT #1	2016-07-11 09:26
MOT test number	359800441802
Result	✓ Passed
Advice Both front tyres wearing on inners	

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	64
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MAZDA salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

Owner history	
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

Plate changes	More info >
See in this check if this MAZDA had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-06-11
Last registration	2023-07-03
Complete history	See info



Registration #1	2013-06-11	17 mi
Registration #2	2016-07-11	32.226 mi
Registration #3	2017-03-31	39.542 mi
Registration #4	2018-03-22	50.157 mi
Registration #5	2019-03-30	56.802 mi
Registration #6	2020-03-16	64.253 mi
Registration #7	2021-03-19	68.041 mi
Registration #8		11.177 es
Registration #9		11.777 mi
Registration #10		11.177 es
Registration #11		11.177 ms
Registration #12		11.777 es
Registration #13		71.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Safety ratings

NCAP rating	****
Adult	94%
Children	87%
Pedestrian	64%
Safety systems	86%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1670 mm
Length	4540 mm
Wheel base	2700 mm
Kerb weight	1530 kg
Max. allowed weight	2110 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	SH 30334984

CarCheck.co.uk page 12/12