



report date: 2024-03-29

General information

Make	VAUXHALL
Model	COMBO 2300 L1H1 CDTi S/S ECOFLEX
Colour	White
Year of manufacture	2016
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	58.9 mpg
CO2 emission	126 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-01-22
Pictures	9
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-04-11
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	5
Total items failed	10
MOT #8	2023-04-12 09:01
MOT test number	718319654480
Result	✓ Passed
Next expiry date	2024-04-11
MOT #7	2022-01-29 15:52
MOT test number	475381203441
Result	✓ Passed
MOT #6	2021-01-04 14:09
MOT test number	637092741692
Result	✓ Passed
MOT #5	2021-01-04 12:22
MOT test number	368688717923
Result	✗ Failed
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Fail	Offside Rear Shock absorbers damaged to the extent that it does not function (5.3.2 (b))



MOT #4	2020-09-18 11:38
MOT test number	769901857701
Result	✓ Passed
Advice	Front Road wheel slightly distorted both slightly damaged around rim area (5.2.2 (c) (i))

MOT #3	2020-09-10 12:38
MOT test number	414575415624
Result	✗ Failed
Advice	Front Road wheel slightly distorted both slightly damaged around rim area (5.2.2 (c) (i))
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
Fail	Headlamp aim not tested (4.1.2 (b))
Fail	Horn not working (7.7 (a) (ii))
Fail	Offside Front Macpherson strut mounting damaged and seriously weakened The bearing seems as though it has collapsed (5.3.3 (b) (i))
Fail	Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Windscreen washer not working (3.5 (a))

MOT #2	2019-09-12 15:35
MOT test number	267723250796
Result	✓ Passed
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))



MOT #1	2019-09-11 14:46
MOT test number	380811526459
Result	✗ Failed
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Minor	Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Fail	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))



Tax & MOT check

X

Untaxed

Tax expired:
31 May 2023

X

MOT

Expired:
11 April 2024

Tax status	Expired at 31 May 2023
Days left	334 days too late
MOT expiry date	11 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 FN66LZK
Plate since	2019-06-29
Current registration	 FN66LZK
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-09-14
Last registration	2023-04-12
Complete history	See info



Registration #1	2016-09-14	16 mi
Registration #2	2019-09-11	69.180 mi
Registration #3	2019-09-12	69.180 mi
Registration #4	2020-09-10	75.239 mi
Registration #5	2020-09-18	75.240 mi
Registration #6	2020-09-20	75.240 mi
Registration #7	2020-09-20	75.240 mi
Registration #8	2020-09-20	75.240 mi
Registration #9	2020-09-20	75.240 mi
Registration #10	2020-09-20	75.240 mi

More info >



Dimensions & weight

Width	2119 mm
Height	1845 mm
Length	4390 mm
Wheel base	2750 mm
Kerb weight	1290 kg
Max. allowed weight	2290 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	263A20006121701 LN9