



report date: 2024-03-29

General information

Make	VOLVO
Model	V70 D3 R-DESIGN
Colour	Blue
Year of manufacture	2011
Top speed	130 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Engine capacity	1.984 cc
Cylinders	5
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	144 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-12-15
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-18
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	9
Total items failed	7

MOT #15	2023-05-19 12:43
MOT test number	675952283359
Result	✓ Passed
Next expiry date	2024-05-18
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

MOT #14	2022-07-07 11:59
MOT test number	386398647060
Result	✓ Passed
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #13	2021-11-18 13:22
MOT test number	984361490372
Result	✓ Passed

MOT #12	2021-11-18 11:37
MOT test number	860729754275
Result	✗ Failed
Fail	Offside Rear Tyre has ply or cords exposed cut with cords exposed in middle band of tyre (5.2.3 (d) (ii))

**MOT #11** 2020-10-29 14:36**MOT test number** 386778483736**Result** ✓ Passed**Advice** Central Exhaust mounting defective (6.1.2 (a))**MOT #10** 2019-04-26 13:35**MOT test number** 971261023962**Result** ✓ Passed**MOT #9** 2019-04-26 11:00**MOT test number** 311680975295**Result** ✗ Failed**Fail** Nearside Rear Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #8** 2018-04-26 11:38**MOT test number** 304147607266**Result** ✓ Passed**MOT #7** 2017-05-03 10:16**MOT test number** 315063170578**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-04-29 14:38**MOT test number** 385191885897**Result** ✓ Passed

**MOT #5** 2016-04-29 11:52**MOT test number** 896785427468**Result** ✗ Failed

Fail Nearside Front Trailing arm rubber bush bonding deteriorated resulting in excessive movement
(2.4.G.2)

Fail Offside Front Trailing arm rubber bush bonding deteriorated resulting in excessive movement
(2.4.G.2)

MOT #4 2015-05-06 14:58**MOT test number** 229546025414**Result** ✓ Passed

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)

MOT #3 2015-05-06 12:12**MOT test number** 669976525128**Result** ✗ Failed

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
(4.1.D.1a)

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement
(2.4.G.2)

MOT #2 2014-03-12 15:36**MOT test number** 708891174029**Result** ✓ Passed**MOT #1** 2014-03-12 10:21**MOT test number** 585751074091**Result** ✗ Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
18 May 2024

Tax status	Valid until 1 May
Days left	367
MOT expiry date	18 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	GL60VJZ
Plate since	2024-03-29
Current registration	GL60VJZ
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-01-31
Last registration	2023-05-19
Complete history	See info



Registration #1	2011-01-31	9 mi
Registration #2	2014-03-12	18.113 mi
Registration #3	2014-03-12	18.113 mi
Registration #4	2015-05-06	24.931 mi
Registration #5	2015-05-06	24.931 mi
Registration #6	2016-04-29	30.756 mi
Registration #7	2016-04-29	30.756 mi
Registration #8	2017-05-03	35.010 mi
Registration #9	2018-04-26	39.785 mi
Registration #10	2019-05-20	45.510 mi
Registration #11	2019-05-20	45.510 mi
Registration #12	2019-05-20	45.510 mi
Registration #13	2019-05-20	45.510 mi
Registration #14	2019-05-20	45.510 mi
Registration #15	2019-05-20	45.510 mi
Registration #16	2019-05-20	45.510 mi
Registration #17	2019-05-20	45.510 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1861 mm
Height	1547 mm
Length	4823 mm
Wheel base	2816 mm
Kerb weight	1752 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	846923