





General information

Make	ΤΟΥΟΤΑ
Model	VERSO VALVEMATIC TR
Colour	Silver
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	132 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G





Internet history

Entry 1

Date

Pictures

2022-06-14

8

Listing price

View report





source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	14
Total items failed	11

MOT #14	2024-01-25 15:22
MOT test number	617492702282
Result	✓ Passed
Next expiry date	2025-01-30
Minor Offside Front Anti-roll bar linkage ball joint dust cover severely deterio	orated (5.3.4 (b) (i))

MOT #13	2024-01-25 14:19
MOT test number	795579744911
Result	🗙 Failed
MinorOffside Front Anti-roll bar linkage ball joint dust cover severely deFailRear Registration plate lamp inoperative in the case of a single lamp	
Advice Nearside Rear Nail in tyre	

MOT #12		2023-01-31 17:16
MOT test r	number	193046614105
Result		✓ Passed
Advice Advice (e))	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Tyre worn close to legal limit/worn on edge Heavily worn in	side edge also (5.2.3



MOT #11		2023-01-26 11:29
MOT test n	umber	747362032512
Result		🗙 Failed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Hor	n not working (7.7 (a))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge Heavily worn inside edge also (5.2.3 (e))		
Advice	Exhaust has a minor leak of exhaust gases Centre section (6.1.2 (a))	

MOT #10	2022-01-21 12:55
MOT test number	484973416114
Result	✓ Passed

МОТ #9	2022-01-21 09:32
MOT test number	539333946218
Result	× Failed
Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
Fail Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))	

MOT #8	2021-01-14 10:53
MOT test number	849615032141
Result	✓ Passed

MOT #7	2020-01-14 17:10
MOT test number	298428519905
Result	✓ Passed



GU12XLP
report date: 2024-03-29

MOT #6 20	20-01-07 11:07
MOT test number	132338974309
Result	🗙 Failed
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge WORN ON BOTH EDGES E UNDERINFLATION (5.2.3 (e))	DUE TO
Fail Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge WORN ON BOTH EDGES DU UNDERINFLATION (5.2.3 (e))	JE TO
Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))	
Fail Nearside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	

MOT #5	2019-01-09 10:33
MOT test number	732733463703
Result	✓ Passed
MOT #4	2017-12-12 15:01
MOT test number	107208804178
Result	✓ Passed
MOT #3	2017-03-16 14:11
MOT test number	460103702276
Result	✓ Passed
MOT #2	2016-03-21 14:42
MOT test number	497703337856
Result	✓ Passed





MOT #1	2015-03-16 14:33
MOT test number	546185175044
Result	✓ Passed
Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)	



Tax & MOT check

√ Taxed	√ MOT
Tax due: 1 July 2024	Expires: 30 January 2025
Tax status	Valid until 1 July
Days left	62
MOT expiry date	30 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Lamp
Туре	K K K K K K K K K K K K K K K K K K K
Damage 2	AMPLE
Damage 2	
Date	 *
Category	 amer
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow



GU12XLP report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-03-26
Last registration	2024-01-25
Complete history	<u>See info</u>



Registration #1	2012-03-26	13 mi
Registration #2	2015-03-16	10.805 mi
Registration #3	2016-03-21	14.385 mi
Registration #4	2017-03-16	16.893 mi
Registration #5	2017-12-12	19.052 mi
Registration #6	2019-01-09	30.597 mi
Registration #7	2020-01-07	45.144 mi
Registration #8	2020-01-14	45.481 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi
Registration #16		11.277 est

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1505 kg
Max. allowed weight	2125 kg
Additional information	
Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13