



report date: 2024-03-28

General information

Make	JAGUAR
Model	XKR
Colour	Black
Year of manufacture	2010
Top speed	155 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	510 BHP
Max. torque	625 Nm at 4.000 rpm
Engine capacity	5.000 cc
Cylinders	8
Fuel type	Petrol
Consumption city	14.9 mpg
Consumption extra urban	32.8 mpg
Consumption combined	23.0 mpg
CO2 emission	292 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-12-21
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-09-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	16
Total items failed	6

MOT #13	2023-09-22 09:03
MOT test number	671198255774
Result	✓ Passed
Next expiry date	2024-09-21

MOT #12	2023-09-22 09:03
MOT test number	798037361020
Result	✗ Failed
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #11	2022-11-14 08:53
MOT test number	474708732884
Result	✓ Passed

**MOT #10**

2021-11-23 17:41

**MOT test number**

541674881178

**Result**

✓ Passed

**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #9**

2021-11-22 09:07

**MOT test number**

582566950552

**Result**

✗ Failed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail** Offside Front Outline marker lamp not working (4.2.1 (a) (ii))

**Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #8**

2020-11-23 10:46

**MOT test number**

589727961828

**Result**

✓ Passed

**MOT #7** 2019-05-20 12:03**MOT test number** 601915926388**Result** ✓ Passed**MOT #6** 2018-05-15 11:51**MOT test number** 152610477737**Result** ✓ Passed**Advice** Nearside Rear Lower Suspension arm has slight play in a pin/bush Hub bush (2.4.G.2)**MOT #5** 2017-05-09 14:21**MOT test number** 157812422275**Result** ✓ Passed**Advice** Engine management light staying on**Advice** Front tyres wearing on inner edges**MOT #4** 2016-05-10 08:15**MOT test number** 821654042060**Result** ✓ Passed**MOT #3** 2015-04-27 17:11**MOT test number** 298077215106**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2014-05-21 08:25**MOT test number** 517261144108**Result** ✓ Passed



MOT #1	2013-09-25 14:01
MOT test number	759278363286
Result	✓ Passed
Advice	Nearside Rear Shock absorber has a slightly worn bush (2.7.4)
Advice	Offside Rear Shock absorber has a slightly worn bush (2.7.4)



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-10-21
Last registration	2023-09-22
Complete history	<a href="#">See info</a>



Registration #1	2010-10-21	8 mi
Registration #2	2013-09-25	21.745 mi
Registration #3	2014-05-21	22.755 mi
Registration #4	2015-04-27	28.757 mi
Registration #5	2016-05-10	32.559 mi
Registration #6	2017-05-09	39.410 mi
Registration #7	2018-05-15	51.551 mi
Registration #8	2019-05-20	63.690 mi
Registration #9	2020-05-20	75.831 mi
Registration #10	2021-05-20	87.972 mi
Registration #11	2022-05-20	100.113 mi
Registration #12	2023-05-20	112.254 mi
Registration #13	2024-05-20	124.395 mi
Registration #14	2025-05-20	136.536 mi
Registration #15	2026-05-20	148.677 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	78%
Children	65%
Pedestrian	43%
Safety systems	71%
Overall rating	68%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1892 mm
Height	1329 mm
Length	4794 mm
Wheel base	2752 mm
Kerb weight	1800 kg
Max. allowed weight	2185 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	10022109142508PS