



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 LOOK
Colour	Grey
Year of manufacture	2008
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-02
Pictures	22
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-29
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	61
Total items failed	10

MOT #18	2023-10-30 09:54
---------	------------------

MOT test number	201542294540
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-10-29
------------------	------------

- Advice** Gear linkage worn
- Advice** Play in steering rack inner joint(s) Advise to replace
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Gearbox mounting defective
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Integral body structure is deformed but structural rigidity is not significantly reduced (6.1.1 (a) (i))

**MOT #17**

2023-10-23 14:15

MOT test number

809230640352

Result**✗ Failed****Advice** Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Fail** Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction (3.1 (a) (ii))**Advice** Integral body structure is deformed but structural rigidity is not significantly reduced (6.1.1 (a) (i))**Advice** Gear linkage worn**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Gearbox mounting defective**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Fail** Rear fog lamp not working (4.5.1 (a) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Play in steering rack inner joint(s) Advise to replace**Fail** Offside Headlamp insecure (4.1.1 (c))

**MOT #16**

2022-10-20 11:12

MOT test number

120211455605

Result

✓ Passed

- Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened face (1.1.14 (a) (ii))
- Advice** Play in steering rack inner joint(s)
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Nail in tyre
- Advice** Sump rusty

MOT #15

2021-10-08 13:04

MOT test number

962979363400

Result

✓ Passed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Front Both Sides Brake disc are corroded
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #14** 2021-10-05 15:13**MOT test number** 878259327700**Result** ✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Minor** Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Various corrosion underneath
- Fail** Oil leaking excessively from transmission underneath (8.4.1 (a) (i))
- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Power steering component has slight seepage from a component (2.1.5 (a))
- Advice** Front Both Sides Brake disc are corroded

MOT #13 2020-10-16 08:08**MOT test number** 757561055795**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2020-10-03 08:33**MOT test number** 428084935580**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear fog lamp not working cover broken and wires broken (4.5.1 (a) (ii))

**MOT #11**

2019-10-22 16:32

MOT test number

442957692206

Result

✓ Passed

- Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Nearside Front Inner Suspension rod ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Inner Suspension rod ball joint has slight play (5.3.4 (a) (i))

MOT #10

2018-09-28 08:27

MOT test number

792004617655

Result

✓ Passed

- Advice** Play in steering rack inner joint(s)

MOT #9

2018-09-25 16:24

MOT test number

700697851315

Result

✗ Failed

- Fail** Central Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Power steering inoperative (2.1.5 (c) (i))
- Advice** Play in steering rack inner joint(s)
- Fail** Battery insecure and likely to fall from carrier (4.13 (a) (ii))

**MOT #8** 2017-08-18 12:56**MOT test number** 265850163699**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Play in steering rack inner joint(s)**Advice** Exhaust system rusty**MOT #7** 2017-08-18 10:45**MOT test number** 563317418987**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Exhaust system rusty**Advice** Play in steering rack inner joint(s)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2016-06-16 09:06**MOT test number** 724783937451**Result** ✓ Passed**Advice** Offside Front Inner Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-06-20 13:31**MOT test number** 747761175135**Result** ✓ Passed**MOT #4** 2014-06-03 11:47**MOT test number** 948134354142**Result** ✓ Passed

**MOT #3** 2013-06-19 11:13**MOT test number** 616160773106**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Cut n/s/r tyre tread**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Small chips front screen**Notice** Exhaust rusting**MOT #2** 2012-06-06 11:01**MOT test number** 985098252147**Result** ✓ Passed**Notice** Exhaust rusting**Notice** Nail in nearside front tyre**MOT #1** 2011-06-14 09:28**MOT test number** 868875561192**Result** ✓ Passed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
29 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	29 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	MM08PKE
Plate since	2019-09-28
Current registration	MM08PKE
Plate since	2019-09-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-06-28
Last registration	2023-10-30
Complete history	See info



Registration #1	2008-06-28	17 mi
Registration #2	2011-06-14	15.254 mi
Registration #3	2012-06-06	19.541 mi
Registration #4	2013-06-19	22.862 mi
Registration #5	2014-06-03	27.711 mi
Registration #6	2015-06-20	35.171 mi
Registration #7	2016-06-16	43.183 mi
Registration #8	2017-08-18	46.640 mi
Registration #9	2017-08-18	46.640 mi
Registration #10	2018-09-25	56.459 mi
Registration #11	2019-06-20	65.377 mi
Registration #12	2020-06-20	75.377 mi
Registration #13	2021-06-20	85.377 mi
Registration #14	2022-06-20	95.377 mi
Registration #15	2023-06-20	105.377 mi
Registration #16	2024-06-20	115.377 mi
Registration #17	2025-06-20	125.377 mi
Registration #18	2026-06-20	135.377 mi
Registration #19	2027-06-20	145.377 mi
Registration #20	2028-06-20	155.377 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	FST65823851