





report date: 2024-03-28

General information

Make	JAGUAR
Model	XK8 COUPE
Colour	Silver
Year of manufacture	2003
Top speed	155 mph
0 - 60 mph	6.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	300 BHP
Max. torque	411 Nm at 4.100 rpm
Engine capacity	4.196 cc
Cylinders	8
Fuel type	Petrol
Consumption city	16.9 mpg
Consumption extra urban	34.0 mpg
Consumption combined	25.0 mpg
CO2 emission	284 g/km
CO2 label	M



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-15

Pictures 51

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-06
MOT pass rate	95 %
MOT passed	18
Failed MOT tests	1
Total advice items	40
Total items failed	1

MOT #19	2023-10-30 15:37
MOT test number	416757818656
Result	✓ Passed
Next expiry date	2024-11-06

MOT #18		2022-10-14 08:33
MOT test	number	378200410300
Result		✓ Passed
Advice	Nearside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice movement	Nearside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting it deteriorated (5.3.4 (a) (i))	n excessive
Advice	Offside Front Lower Shock absorbers has a slightly worn bush (5.3.2 (c))	
Advice deteriorate	Offside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in ed (5.3.4 (a) (i))	excessive movement

MOT #17	2021-10-15 08:51
MOT test number	531468842883
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Advice

Rear Drive shaft joint worn, but not excessively both sides (6.1.7 (c) (i))

Advice

Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #15 2019-11-01 14:02 **MOT** test number 589017957175 Result ✓ Passed Slight play in both rear drive shaft universal joints **Advice Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Offside Front lower arm ball joint boot slightly deteriorated **Advice** Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Nearside Front upper and lower arm boots slightly deteriorated

MOT #14		2018-11-02 11:57
MOT test	numbor	159684417207
MOT test	number	159084417207
Result		✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice (a) (i))	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excess	ssive movement (5.3.4
Advice	Slight play to n/s and o/s/r drive shaft outer universal joints	
Advice	Offside Front lower swivel joint boot slightly deteriorated but prevents the i	ngress of dirt
Advice (5.3.4 (a) (Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in exc i))	cessive movement
Advice dirt	Nearside Front upper and lower swivel joint boots slightly deteriorated but	prevent the ingress of

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #13 2017-11-02 10:19

MOT test number 621274048947

Result
✓ Passed

Advice Nearside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

Advice Nearside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Upper Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Offside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Track rod end ball joint dust cover deteriorated, but preventing the ingress of dirt (2.2.C.1c)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Lower Front suspension ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Rear Anti-roll bar linkage rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #12 2016-10-14 11:11

MOT test number 597681735663

Result
✓ Passed

MOT #11 2016-10-13 11:08

MOT test number 595625983363

Result X Failed

Fail Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #10 2015-10-13 11:58

MOT test number 100833398694

Result
✓ Passed

Advice Steering system has slight free play detected at steering wheel (2.2.A.1b)

CarCheck.co.uk page 5/13



MOT #9 2014-11-03 11:47

MOT test number 187787504353

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Notice N/S and O/S/R has slight play in U/J's

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #8 2013-10-21 11:29

MOT test number 685144593245

Notice N/S and O/S/R wheels have slight play from driveshafts

MOT #7 2012-11-02 11:47

MOT test number 145507202361

Result \(\sqrt{Passed} \)

Advice Rear registration plate delaminated but not likely to be misread (6.3.1d)

Advice Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #6 2011-10-19 12:12

MOT test number 548352891201

Result \(\sqrt{Passed} \)

Advice Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #5 2010-10-25 12:50

MOT test number 743688990286

Result ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT test number

Result

Notice Nail in nearside rear tyre

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2008-10-27 15:53

MOT test number 481041108302

Result ✓ Passed

MOT test number
922125107304

Result

Advice Nearside Front brake disc slightly pitted (3.5.1h)

Advice Nearside Rear brake disc slightly pitted (3.5.1h)

Advice Offside Front brake disc slightly scored (3.5.1h)

Advice Offside Rear brake disc slightly pitted (3.5.1h)

 MOT #1
 2006-10-17 10:36

 MOT test number
 591360296232

 Result
 ✓ Passed

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		AR

	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	NK NE	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-11-06
Last registration	2023-10-30
Complete history	See info



Registration #1	2003-11-06	24 mi
Registration #2	2006-10-17	8.892 mi
Registration #3	2007-11-01	10.563 mi
Registration #4	2008-10-27	11.077 mi
Registration #5	2009-11-03	11.484 mi
Registration #6	2010-10-25	12.565 mi
Registration #7	2011-10-19	14.266 mi
Registration #8	2012-11-02	15.525 mi
Registration #9	2013-10-21	17.128 mi
Registration #10	2014-11-03	17.969 mi
Registration #11	2015-10-13	19.853 mi
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		D.777 es
Registration #21		11.777 mi

More info >

CarCheck.co.uk page 12/13



			_		
- 11	manc	Innc	λ.	$M \cap M$	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	2015 mm
Height	1296 mm
Length	4760 mm
Wheel base	2588 mm
Kerb weight	1685 kg

Additional information

Fuel tank capacity	75 I	
Fuel delivery	Multi-Point Injection	
Number of doors	2	
Engine number	2B0301141116	

CarCheck.co.uk page 13/13