





report date: 2024-03-29

General information

Make	VOLVO
Model	XC90 D5 POWERPULSE R-DESIGN PRO AWD
Colour	Grey
Year of manufacture	2018
Top speed	137 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	231 BHP
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption combined	34.5 mpg
CO2 emission	173 g/km
CO2 label	Н



CarCheck.co.uk page 1/10



Internet history

Entry 2

Date 2022-01-15

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2021-12-16
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/10



MOT history

MOT expiry date	2024-12-28
MOT pass rate	100 %
MOT passed	4
Failed MOT tests	0
Total advice items	3
Total items failed	0

MOT #4	2023-12-28 14:43
MOT test number	781345275459
Result	✓ Passed
Next expiry date	2024-12-28

MOT #3		2022-12-02 14:12
MOT test	number	929855535117
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #2	2021-12-29 15:17
MOT test number	328131042644
Result	✓ Passed
MOT #1	2021-08-05 13:43
MOT test number	982158131602
Result	✓ Passed

CarCheck.co.uk page 3/10



Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	28 December 2024
Full MOT history	See MOT history

Tax calculation

-	
Vehicle class	49
Band	J
First licence fee (12 months)	£ 1.040,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.565,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 4/10



NK18XLO

report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

e when miscory		
For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it		

	More info >	
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		9
Current registration	UK NE	
Plate since		
Current registration	UK UK	
Plate since		
	More info >	

CarCheck.co.uk page 7/10



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 8/10



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-03
Last registration	2023-12-28
Complete history	See info



Registration #1	2018-03-03	16 mi
Registration #2	2021-08-05	16.110 mi
Registration #3		11.777 es
Registration #4	2021-12-29	16.836 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 9/10



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	97%
Children	87%
Pedestrian	72%
Safety systems	94%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2008 mm
Height	1776 mm
Length	4950 mm
Max. allowed weight	2750 kg

Additional information

Number of seats	7
Number of axles	2
Engine number	2488450

CarCheck.co.uk page 10/10