



PEUGEOT



report date: 2024-03-28

General information

| | |
|---------------------|--------------------------|
| Make | PEUGEOT |
| Model | EXPERT HDI 1200 L2H2 P/V |
| Colour | White |
| Year of manufacture | 2012 |
| Top speed | 102 mph |
| 0 - 60 mph | 13.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 128 BHP |
| Max. torque | 320 Nm at 2.000 rpm |
| Engine capacity | 1.997 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 34.9 mpg |
| Consumption extra urban | 42.8 mpg |
| Consumption combined | 39.8 mpg |
| CO2 emission | 186 g/km |
| CO2 label | J |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-03 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2025-04-19 |
| MOT pass rate | 56 % |
| MOT passed | 5 |
| Failed MOT tests | 4 |
| Total advice items | 16 |
| Total items failed | 9 |

| | |
|------------------|--|
| MOT #9 | 2019-11-29 13:18 |
| MOT test number | 260824002169 |
| Result | ✓ Passed |
| Next expiry date | 2020-11-28 |
| Advice | Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) |
| Advice | Nearside Front tyre unevenly worn |

| | |
|-----------------|--|
| MOT #8 | 2019-11-25 11:17 |
| MOT test number | 221209567626 |
| Result | ✗ Failed |
| Advice | Nearside Front tyre unevenly worn |
| Fail | Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) |
| Fail | Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |
| Advice | Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) |

**MOT #7**

2018-10-29 10:12

MOT test number

867207048912

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Also low on tread (5.2.3 (d) (ii))**Advice** Offside Rear Nail in tyre**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))**MOT #6**

2018-10-26 11:04

MOT test number

667459772937

Result

✗ Failed

Fail Nearside Windscreen washer not working (3.5 (a))**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Also low on tread (5.2.3 (d) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Windscreen washer not working (3.5 (a))**Advice** Offside Rear Nail in tyre**Advice** Offside Front Seat belt slightly damaged (7.1.2 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #5**

2017-11-15 14:38

MOT test number

504998886942

Result

✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2017-11-14 09:58**MOT test number** 680791912212**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #3** 2016-11-03 15:28**MOT test number** 126662184660**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #2** 2015-11-09 14:41**MOT test number** 400685331062**Result** ✓ Passed**MOT #1** 2015-11-06 10:03**MOT test number** 916160458057**Result** ✗ Failed**Advice** Front pads low**Fail** Offside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
19 April 2025

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 November |
| Days left | 185 |
| MOT expiry date | 19 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|----------------------------------|------------|
| Vehicle class | 39 |
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | OV62MYH |
| Plate since | 2024-03-28 |
| Current registration | OV62MYH |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


| | |
|-------------------|-------------|
| Finance company | XXXXXXXX XX |
| Date of agreement | XXXXXXXX XX |
| Agreement type | XXXXXXXX XX |
| Agreement term | XXXXXXXX XX |
| Agreement number | XXXXXXXX XX |
| Contact info | XXXXXXXX XX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 11 |
| First mileage registration | 2012-11-29 |
| Last registration | 2019-11-29 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2012-11-29 | 15 mi |
| Registration #2 | 2015-11-06 | 11.896 mi |
| Registration #3 | 2015-11-09 | 11.896 mi |
| Registration #4 | 2016-11-03 | 15.819 mi |
| Registration #5 | 2017-11-14 | 33.401 mi |
| Registration #6 | 2017-11-15 | 33.402 mi |
| Registration #7 | 2019-11-29 | 35.377 mi |
| Registration #8 | 2019-11-29 | 35.377 mi |
| Registration #9 | 2019-11-29 | 35.377 mi |
| Registration #10 | 2019-11-29 | 35.377 mi |
| Registration #11 | 2019-11-29 | 35.377 mi |

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 80 l |
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 3 |
| Engine number | DYZG4031868 |