



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI ACTIVE BLUE DRIVE
Colour	Grey
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	80.7 mpg
Consumption combined	76.3 mpg
CO2 emission	97 g/km
CO2 label	A






Internet history

Entry 2


Date	2022-08-20
Pictures	38
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-05-25
Pictures	11
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-17
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	22
Total items failed	1

MOT #13 2023-05-16 14:33

MOT test number 287991897194

Result ✓ Passed

Next expiry date 2024-05-17

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2023-05-15 12:09

MOT test number 495057502252

Result ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2022-05-18 12:30

MOT test number 717114092491

Result ✓ Passed

**MOT #10**

2022-05-17 13:53

MOT test number

720805061546

Result**✗ Failed**

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MAJOR Parking brake efficiency below requirements (1.4.2 (a) (i))

MAJOR Offside Rear Parking brake inoperative on one side (1.4.1 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9

2021-05-17 13:36

MOT test number

622540248102

Result**✓ Passed**

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8

2020-10-08 12:41

MOT test number

550725629632

Result**✓ Passed**

Advice Tyre slightly damaged/cracking or perishing ALL 4 195/65/15 (5.2.3 (d) (ii))

MOT #7

2019-04-04 10:42

MOT test number

666626373999

Result**✓ Passed**

Advice O/S REAR TYRE CUT AT THE SIDE WALL ALMOST TO EXCESS

Advice N/S REAR TYRE CUT AROUND THE TREAD

**MOT #6** 2019-04-04 09:03**MOT test number** 532006556905**Result** ✗ Failed**Advice** O/S REAR TYRE CUT AT THE SIDE WALL ALMOST TO EXCESS**MAJOR** Front Registration plate does not conform to the specified requirements DELAMINATED (0.1 (d))**Advice** N/S REAR TYRE CUT AROUND THE TREAD**MOT #5** 2018-04-02 09:39**MOT test number** 936236697748**Result** ✓ Passed**MOT #4** 2017-03-17 12:07**MOT test number** 768258388229**Result** ✓ Passed**Advice** Nearside Side repeater slightly discoloured (1.4.A.2f)**Advice** Offside Side repeater slightly discoloured (1.4.A.2f)**MOT #3** 2016-04-04 12:04**MOT test number** 127972801874**Result** ✓ Passed**MOT #2** 2016-04-03 12:30**MOT test number** 665665313661**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)



MOT #1	2015-04-04 10:46
MOT test number	745184095090
Result	✓ Passed
Notice	Front wiper blades split
Notice	All 4 tyres cracking between treads



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
17 May 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	17 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EA12VVN
Plate since	2019-09-28
Current registration	EA12VVN
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2012-04-04
Last registration	2023-05-16
Complete history	See info



Registration #1	2012-04-04	23 mi
Registration #2	2015-04-04	22.387 mi
Registration #3	2016-04-03	28.302 mi
Registration #4	2016-04-04	28.308 mi
Registration #5	2017-03-17	34.840 mi
Registration #6	2018-04-02	40.475 mi
Registration #7	2019-04-04	42.224 mi
Registration #8	2019-04-04	42.224 mi
Registration #9	2019-04-04	42.224 mi
Registration #10	2019-04-04	42.224 mi
Registration #11	2019-04-04	42.224 mi
Registration #12	2019-04-04	42.224 mi
Registration #13	2019-04-04	42.224 mi
Registration #14	2019-04-04	42.224 mi
Registration #15	2019-04-04	42.224 mi
Registration #16	2019-04-04	42.224 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1780 mm
Height	1470 mm
Length	4300 mm
Wheel base	2650 mm
Kerb weight	1360 kg
Max. allowed weight	1810 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

D4FBCZ386102