






report date: 2024-03-29

General information

| Make | FORD |
|---------------------|-------------------|
| Model | KUGA VIGNALE TDCI |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 124 mph |
| 0 - 60 mph | 10.0 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 177 BHP |
|-------------------------|---------------------|
| Max. torque | 400 Nm at 2.000 rpm |
| Engine capacity | 1.997 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 42.2 mpg |
| Consumption extra urban | 44.1 mpg |
| Consumption combined | 2.8 mpg |
| CO2 emission | 160 g/km |
| CO2 label | G |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-12-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-11-21 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 3 |
| Failed MOT tests | 1 |
| Total advice items | 11 |
| Total items failed | 1 |

| MOT #4 | | 2023-11-20 08:34 |
|-----------|--|------------------|
| MOT test | number | 938976470430 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-11-21 |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords | (5.2.3 (d) (i)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Oil leak, but not excessive Underside of engine (8.4.1 (a) (i)) | |

| MOT #3 | | 2023-11-17 11:06 |
|---------------|--|------------------------|
| MOT test | number | 146441278993 |
| Result | | × Failed |
| Advice | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2 | .3 (d) (i)) |
| Fail N | earside Front Tyre has a bulge, caused by separation or partial failure of its struc | cture (5.2.3 (d) (ii)) |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Oil leak, but not excessive Underside of engine (8.4.1 (a) (i)) | |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

CarCheck.co.uk page 3/11



 MOT #2
 2022-11-17 12:03

 MOT test number
 123609055535

 Result
 ✓ Passed

MOT #1 2021-11-22 13:14

MOT test number 127372153142

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 January |
|------------------|-----------------------|
| Days left | 246 |
| MOT expiry date | 21 November 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|--------------|
| Band | I |
| First licence fee (12 months) | £ 645,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 1.040,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is | |
|--|-------------|
| | |
| THE STATE OF THE S | |
| *************************************** | |
| *************************************** | |
| | |
| THE PARTY OF THE P | |
| *************************************** | |
| ************* | |
| | More info > |
| | , , |
| Plate changes | |
| See in this check if this FORD had different number plates. | |
| | |
| Number of plates | |
| Current registration | UK UK |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2018-11-22 |
| Last registration | 2023-11-20 |
| Complete history | See info |



| Registration #1 | 2018-11-22 | 13 mi |
|-----------------|------------|------------|
| Registration #2 | 2021-11-22 | 22.646 mi |
| Registration #3 | | 11,777 mi |
| Registration #4 | | 71,777 es |
| Registration #5 | | 71,777 66 |
| Registration #6 | | 10.777 esi |

More info >

page 10/11 CarCheck.co.uk



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 86% |
| Pedestrian | 70% |
| Safety systems | 100% |
| Overall rating | 88% |
| Video | see crash video |



Dimensions & weight

| Width | 1856 mm |
|---------------------|---------|
| Height | 1689 mm |
| Length | 4541 mm |
| Wheel base | 2690 mm |
| Kerb weight | 1815 kg |
| Max. allowed weight | 2230 kg |

Additional information

| Fuel delivery | Direct Injection |
|-----------------------------------|------------------|
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles Carcheck.co.uk | 2 page 11/1: |

JP28576