





report date: 2024-03-28

General information

Make	ТОУОТА
Model	URBAN CRUISER D-4D
Colour	Blue
Year of manufacture	2010
Top speed	109 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	205 Nm at 1.800 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-05-22
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	34
Total items failed	0

MOT #14	2023-05-23 09:24
MOT test number	480241421778
Result	✓ Passed
Next expiry date	2024-05-22
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))

MOT #13		2023-05-16 09:49
MOT test	number	896217012400
Result		× Failed
MAJOR	Nearside Front Brake pipe excessively corroded To rear flexi (1.1.11 (c))	
MAJOR	Nearside Rear Brake pipe excessively corroded Flexi to caliper (1.1.11 (c))	
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Front Brake pipe excessively corroded To rear flexi (1.1.11 (c))	
MAJOR	Offside Rear Brake pipe excessively corroded Flexi to calip6 (1.1.11 (c))	

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT #12 2022-01-31 13:54 **MOT** test number 525348886599 Result Passed **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #11 2022-01-31 10:52 **MOT** test number 166301149429 Result × Failed **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **MAJOR** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) **Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) **Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #10		2021-01-27 14:03
MOT test	number	108010280958
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/12



MOT #9

GV59K0E

report date: 2024-03-28

2019-05-28 11:34

MOT test number

Result

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #8 2018-05-30 11:04

MOT test number 495017996327

Result \rightarrow Passed

Advice Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))

MOT #7 2018-05-29 14:28

MOT test number 798413413174

Result X Failed

Advice Offside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake pipe corroded, covered in grease or other material to rear (1.1.11 (c))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #6 2017-05-31 09:41

MOT test number 655669602009

Result \(\sqrt{Passed} \)

Advice Nail in offside rear tyre

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5	2016-06-15 15:47
MOT test number	460514399287
Result	✓ Passed
MOT #4	2015-12-14 15:23
MOT test number	493769425243
Result	✓ Passed
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2014-12-11 11:13
MOT test number	386595044334
Result	✓ Passed
MOT #2	2013-12-12 09:56
MOT test number	227696943356
Result	✓ Passed
MOT #1	2012-12-20 10:01
MOT test number	249395652379

MOT test	number	249395652379
Result		✓ Passed
Notice	Handbrake travel slightly long	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 March
Days left	305
MOT expiry date	22 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*		
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.)TA
THE STATE OF THE S		

	More info	>
Plate changes See in this check if this TOYOTA had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-01-04
Last registration	2023-05-23
Complete history	See info



Registration #1	2010-01-04	18 mi
Registration #2	2012-12-20	29.443 mi
Registration #3	2013-12-12	37.626 mi
Registration #4	2014-12-11	42.508 mi
Registration #5	2015-12-14	48.041 mi
Registration #6	2016-06-15	50.944 mi
Registration #7	2017-05-31	54.340 mi
Registration #8	2018-05-29	64.066 mi
Registration #9		11.777 es
Registration #10		
_		11.777 44
Registration #11		11.777 es
Registration #11 Registration #12		11.777 ea 11.777 ea
		11,777 ea 11,777 ea 11,777 ea
Registration #12		11.77 m

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
S0569	

Safety ratings

NCAP rating	***
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight

Width	1725 mm
Height	1540 mm
Length	3930 mm
Wheel base	2460 mm
Kerb weight	1265 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	42
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number 1ND1128776