



report date: 2024-03-29

General information

|                     |                   |
|---------------------|-------------------|
| Make                | AUDI              |
| Model               | Q7 TDI QUATTRO SE |
| Colour              | Silver            |
| Year of manufacture | 2009              |
| Top speed           | 134 mph           |
| 0 - 60 mph          | 8.5 seconds       |
| Gearbox             | 6 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 242 BHP             |
| Max. torque             | 550 Nm at 2.000 rpm |
| Engine capacity         | 2.967 cc            |
| Cylinders               | 6                   |
| Fuel type               | Diesel              |
| Consumption city        | 25.2 mpg            |
| Consumption extra urban | 37.2 mpg            |
| Consumption combined    | 31.7 mpg            |
| CO2 emission            | 234 g/km            |
| CO2 label               | L                   |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-09-06                  |
| Pictures      | 3                           |
| Listing price | <a href="#">View report</a> |



source: autotrader.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-07-11 |
| MOT pass rate      | 67 %       |
| MOT passed         | 12         |
| Failed MOT tests   | 6          |
| Total advice items | 36         |
| Total items failed | 8          |

## MOT #18 2023-07-10 10:44

MOT test number 911283204880

Result ✓ Passed

Next expiry date 2024-07-11

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Power steering pipe/hose has slight seepage at rack (2.1.5 (a))

## MOT #17 2023-07-10 09:05

MOT test number 358703622754

Result ✗ Failed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Power steering pipe/hose has slight seepage at rack (2.1.5 (a))

**MOT #16** 2022-07-08 11:50**MOT test number** 893538886927**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Side runner fixing brackets protruding slightly**Advice** Oil leak, but not excessive from engine (8.4.1 (a) (i))**MOT #15** 2021-07-12 11:24**MOT test number** 135681987828**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge tyre 3mm worn on edges perished and slight outer sidewall damage (5.2.3 (e))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #14** 2021-07-12 09:16**MOT test number** 775899096923**Result** ✗ Failed**Fail** Front Passenger's seat insecure (6.2.6 (a) (ii))**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge tyre 3mm worn on edges perished and slight outer sidewall damage (5.2.3 (e))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**MOT #13** 2019-12-05 15:45**MOT test number** 425936984507**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12**

2019-11-29 12:41

**MOT test number**

598291459118

**Result****✗ Failed****Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail**

Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice**

Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #11**

2018-12-18 15:05

**MOT test number**

948359771032

**Result****✓ Passed****Minor**

Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #10**

2017-12-20 17:03

**MOT test number**

869727756410

**Result****✓ Passed****MOT #9**

2017-12-20 17:03

**MOT test number**

133499269778

**Result****✗ Failed****Pass with rectification**

Offside Front position lamp(s) not working (1.1.A.3b)



MOT #8 2016-12-28 15:19

MOT test number 360241619897

Result ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2015-12-15 17:32

MOT test number 776045382622

Result ✓ Passed

**Advice** Under trays fitted

**Advice** Engine covers fitted

**Advice** Emissions to clean to print

MOT #6 2015-12-15 17:32

MOT test number 773010199621

Result ✗ Failed

**Advice** Under trays fitted

**Pass with rectification** Nearside Headlamp aim too high (1.8)

**Advice** Engine covers fitted

**Advice** Emissions to clean to print

**MOT #5** 2015-03-03 16:09**MOT test number** 877382965078**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-09-17 10:09**MOT test number** 355430164285**Result** ✓ Passed**MOT #3** 2013-10-23 13:07**MOT test number** 965236293216**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #2** 2013-10-23 13:07**MOT test number** 355416493213**Result** ✗ Failed**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Child seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #1** 2012-10-26 12:20**MOT test number** 538810102327**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
11 July 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 April             |
| <b>Days left</b>        | 337                             |
| <b>MOT expiry date</b>  | 11 July 2024                    |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 49         |
| <b>Band</b>                                    | L          |
| <b>Single payment (12 months)</b>              | £ 675,00,- |
| <b>Single six month payment</b>                | £ 371,25,- |
| <b>Total payable by 12 monthly instalments</b> | £ 708,75,- |





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this AUDI had different number plates.

|                      |                |
|----------------------|----------------|
| Number of plates     | 1              |
| Current registration | <b>OV59DYM</b> |
| Plate since          | 2019-03-29     |
| Current registration | <b>OV59DYM</b> |
| Plate since          | 2019-03-29     |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 19                       |
| First mileage registration | 2009-10-26               |
| Last registration          | 2023-07-10               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2009-10-26 | 21 mi     |
| Registration #2  | 2012-10-26 | 5.501 mi  |
| Registration #3  | 2013-10-23 | 15.546 mi |
| Registration #4  | 2014-09-17 | 21.366 mi |
| Registration #5  | 2015-03-03 | 23.814 mi |
| Registration #6  | 2015-12-15 | 35.715 mi |
| Registration #7  | 2015-12-15 | 35.715 mi |
| Registration #8  | 2016-12-28 | 51.179 mi |
| Registration #9  | 2017-12-20 | 66.196 mi |
| Registration #10 | 2017-12-20 | 66.196 mi |
| Registration #11 | 2018-03-20 | 75.277 mi |
| Registration #12 | 2018-03-20 | 75.277 mi |
| Registration #13 | 2018-03-20 | 75.277 mi |
| Registration #14 | 2018-03-20 | 75.277 mi |
| Registration #15 | 2018-03-20 | 75.277 mi |
| Registration #16 | 2018-03-20 | 75.277 mi |
| Registration #17 | 2018-03-20 | 75.277 mi |
| Registration #18 | 2018-03-20 | 75.277 mi |
| Registration #19 | 2018-03-20 | 75.277 mi |

More info >



Car features

The AUDI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1983 mm |
| Height              | 1737 mm |
| Length              | 5086 mm |
| Wheel base          | 3002 mm |
| Kerb weight         | 3150 kg |
| Max. allowed weight | 3200 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 100 l            |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 7                |

**Engine number**

CCM 001831