





report date: 2024-03-29

General information

Make	CITROEN
Model	C3 PICASSO PURETECH PLATINUM PICASSO
Colour	Purple
Year of manufacture	2016
Top speed	116 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP	
Max. torque	205 Nm at 1.500 rpm	
Engine capacity	1.200 cc	
Cylinders	3	
Fuel type	Petrol	
Consumption city	44.1 mpg	
Consumption extra urban	67.3 mpg	
Consumption combined	56.5 mpg	
CO2 emission	115 g/km	
CO2 label	С	



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2021-07-13

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

Entry 1

Date	2021-07-06
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/12



AO66EXB report date: 2024-03-29

MOT history

MOT expiry date	2024-08-12
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	18
Total items failed	1

MOT #7	202	23-08-04 08:47
MOT test	t number	227504414924
Result		✓ Passed
Next expi	piry date	2024-08-12
Advice (d) (i))	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords si	de wall (5.2.3
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Advice	Central Rear Lower Sub-frame corroded but not seriously weakened light corrosion (5.3.3 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a	a) (ii))

MOT #6		2022-08-02 14:26
MOT test	number	405390114070
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4 2021-08-13 14:56

MOT test number 203537903684

Result ✓ Passed

 MOT #3
 2021-01-29 10:35

 MOT test number
 967894949155

 Result
 ✓ Passed

 MOT #2
 2020-02-07 16:09

 MOT test number
 621837431184

Result \sqrt{Passed}

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #1 2020-02-07 09:26

MOT test number 739437611933

Result X Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge no tread showing on edges (5.2.3 (e))

Minor Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

DANGEROUS Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Minor Offside Front Tyre obviously under inflated (5.2.3 (I))

Advice Nearside Front Tyre worn close to legal limit/worn on edge no tread showing on edges (5.2.3 (e))

Advice Tpms warning light on

Minor Nearside Front Tyre obviously under inflated (5.2.3 (I))

DANGEROUS Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

CarCheck.co.uk page 5/12



AO66EXB report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	12 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



AO66EXB report date: 2024-03-29

Owner history	
For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	SIP:
Plate since	
Current registration	NK SING SING SING SING SING SING SING SING
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-10-14
Last registration	2023-08-04
Complete history	See info



Registration #1	2016-10-14	26 mi
Registration #2	2020-02-07	24.824 mi
Registration #3	2020-02-07	24.824 mi
Registration #4	2021-01-29	33.821 mi
Registration #5		11.777 es
Registration #6		0.00 44
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Safety ratings

NCAP rating	****
Adult	81%
Children	76%
Pedestrian	43%
Safety systems	40%
Overall rating	68%
Video	see crash video



Dimensions & weight

Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1760 kg

Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	XVA30396110

CarCheck.co.uk page 12/12