



HYUNDAI



DUI2ULL

report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI PREMIUM
Colour	Blue
Year of manufacture	2012
Top speed	118 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-04
Pictures	63
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-11-22
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	27
Total items failed	6

MOT #16	2023-11-23 13:48
MOT test number	821396433522
Result	✓ Passed
Next expiry date	2024-11-22

MOT #15	2022-11-08 13:07
MOT test number	150331763735
Result	✓ Passed
<div><div>Advice</div>Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))</div> <div><div>Advice</div>Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))</div> <div><div>Advice</div>Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))</div> <div><div>Advice</div>Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))</div>	

**MOT #14** 2022-11-08 12:16**MOT test number** 828458485390**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Outer Suspension component mounting prescribed area is corroded but not considered excessive sill (5.3.6 (a) (i))**MOT #13** 2021-11-11 14:50**MOT test number** 858771930556**Result** ✓ Passed**MOT #12** 2021-08-27 15:21**MOT test number** 922838658702**Result** ✓ Passed**Advice** Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**MOT #11** 2021-08-05 14:07**MOT test number** 981341649708**Result** ✗ Failed**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**MOT #10** 2020-06-09 08:30**MOT test number** 266239373106**Result** ✓ Passed

**MOT #9**

2019-06-13 08:50

MOT test number

310243204704

Result

✓ Passed

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #8**

2018-06-22 09:56

MOT test number

239571682438

Result

✓ Passed

Advice Covers fitted**Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Rear tyres are scrubbing on the inner edge**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #7**

2017-07-05 08:01

MOT test number

552205417870

Result

✓ Passed

Advice Engine covers and under trays fitted

**MOT #6** 2017-07-04 10:43**MOT test number** 928310201673**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside rear brake binding by hand**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Engine covers and under trays fitted**Fail** Offside Front coil spring broken (2.4.C.1a)**MOT #5** 2017-02-09 12:37**MOT test number** 866862651561**Result** ✓ Passed**MOT #4** 2017-02-09 09:25**MOT test number** 905710218562**Result** ✗ Failed**Fail** Registration plate character(s) incorrectly spaced both (6.3.4a)**MOT #3** 2016-02-25 15:23**MOT test number** 338347983659**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #2 2016-02-25 15:23

MOT test number 832450321374

Result ✗ Failed

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1 2015-02-20 16:05

MOT test number 235971255049

Result ✓ Passed

Notice Under-trays fitted obscuring some underside components

Advice Front registration plate deteriorated but not likely to be misread (6.3.1d)

Notice Engine covers fitted obscuring some components in the engine bay



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
22 November 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	22 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	DU12ULL
Plate since	2019-03-29
Current registration	DU12ULL
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-03-01
Last registration	2023-11-23
Complete history	See info



Registration #1	2012-03-01	21 mi
Registration #2	2015-02-20	40.941 mi
Registration #3	2016-02-25	48.122 mi
Registration #4	2016-02-25	48.122 mi
Registration #5	2017-02-09	58.771 mi
Registration #6	2017-02-09	58.772 mi
Registration #7	2017-07-04	62.826 mi
Registration #8	2017-07-05	62.826 mi
Registration #9	2018-06-22	69.357 mi
Registration #10	2019-06-22	75.377 mi
Registration #11	2019-06-22	75.377 mi
Registration #12	2019-06-22	75.377 mi
Registration #13	2019-06-22	75.377 mi
Registration #14	2019-06-22	75.377 mi
Registration #15	2019-06-22	75.377 mi
Registration #16	2019-06-22	75.377 mi
Registration #17	2019-06-22	75.377 mi
Registration #18	2019-06-22	75.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1659 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDBU032355