



General information

Make	FIAT
Model	500C SPORT
Colour	Red
Year of manufacture	2010
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 6.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	65.7 mpg
Consumption combined	55.4 mpg
CO2 emission	113 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-01-29
Pictures	6
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-03-22
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	28
Total items failed	15

MOT #13	2023-03-23 10:46
MOT test number	524072222758
Result	✓ Passed
Next expiry date	2024-03-22
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))

MOT #12	2022-03-22 16:17
MOT test number	406221938180
Result	✓ Passed
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

**MOT #11**

2022-03-22 14:22

MOT test number

269239891917

Result

✗ Failed

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))**Fail** Front Exhaust silencer likely to become detached clamp corroded away (8.1.1 (b) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front tyre has slight cracks between treads**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #10**

2020-12-29 15:30

MOT test number

293025219584

Result

✓ Passed

MOT #9

2019-05-07 14:02

MOT test number

822864457271

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear exhaust corroded**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Day time running lights inop

**MOT #8**

2019-05-07 14:02

MOT test number

809304386720

Result**✗ Failed****Pass with rectification** Nearside Front Direction indicator not working (4.4.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**Advice** Rear exhaust corroded**Pass with rectification** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Day time running lights inop**MOT #7**

2018-05-10 13:28

MOT test number

572044322256

Result**✓ Passed****Advice** Washer bottle split**Advice** Rear tyres perished**Advice** Exhaust corroded**Advice** Offside Front shock absorber corroded**MOT #6**

2017-04-28 13:24

MOT test number

309404965426

Result**✓ Passed****Advice** Centre rear exhaust corroded



MOT #5	2016-04-18 12:58
MOT test number	339212942481
Result	✓ Passed
Advice	Offside Front accident damage repair

MOT #4	2016-04-13 13:57
MOT test number	748791919937
Result	✗ Failed
Fail	Offside Side repeater incorrect colour (1.4.A.2f)
Fail	Offside Headlamp aim too low (1.8)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
Fail	Nearside Stop lamp not working (1.2.1b)
Fail	Nearside Headlamp aim too high (1.8)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Offside Front accident damage repair
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #3	2015-04-23 12:32
MOT test number	568563915189
Result	✓ Passed



MOT #2	2014-06-25 11:47
MOT test number	527296274114
Result	✓ Passed
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)
Advice	Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)

MOT #1	2013-07-02 16:50
MOT test number	749753483154
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
7 April 2024

X

MOT

Expired:
22 March 2024

Tax status	Expired at 7 April 2024
Days left	22 days too late
MOT expiry date	22 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-06-30
Last registration	2023-03-23
Complete history	See info



Registration #1	2010-06-30	11 mi
Registration #2	2013-07-02	22.431 mi
Registration #3	2014-06-25	26.589 mi
Registration #4	2015-04-23	28.708 mi
Registration #5	2016-04-13	29.683 mi
Registration #6	2016-04-18	29.715 mi
Registration #7	2017-04-28	32.654 mi
Registration #8	2018-05-10	37.084 mi
Registration #9	2019-05-20	38.000 mi
Registration #10	2019-05-20	38.000 mi
Registration #11	2019-05-20	38.000 mi
Registration #12	2019-05-20	38.000 mi
Registration #13	2019-05-20	38.000 mi
Registration #14	2019-05-20	38.000 mi
Registration #15	2019-05-20	38.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1305 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	6058766