



report date: 2024-03-29

## General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 16V
Colour	Silver
Year of manufacture	2006
Top speed	100 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	75 BHP
Max. torque	126 Nm at 3.300 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	48.7 mpg
Consumption combined	39.8 mpg
CO2 emission	170 g/km
CO2 label	H






Internet history

Entry 1

Date	2022-03-18
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-03-16
MOT pass rate	65 %
MOT passed	17
Failed MOT tests	9
Total advice items	53
Total items failed	9

MOT #26	2024-03-12 09:40
MOT test number	463249657264
Result	✓ Passed
Next expiry date	2025-03-16
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #25	2023-03-09 16:41
MOT test number	613255582463
Result	✓ Passed

MOT #24	2023-03-09 14:27
MOT test number	493915668344
Result	✗ Failed
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
MAJOR	Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))

MOT #23	2022-03-17 15:51
MOT test number	694992461352
Result	✓ Passed

**MOT #22**

2021-08-14 10:02

**MOT test number**

812122573164

**Result**

✓ Passed

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn To 2mm (5.2.3 (e))**Advice** Nearside Outer Sill Damaged**Advice** Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement slight play bottom bush (5.3.4 (a) (i))**Advice** Wipers slightly smearing**Advice** Hydraulic leak, but not excessive Power Steering Pipe (8.4.1 (a) (i))**MOT #21**

2021-08-06 16:44

**MOT test number**

376327598912

**Result**

✗ Failed

**MAJOR** Offside Rear Service brake lagging in operation (1.2.1 (d))**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**Advice** Hydraulic leak, but not excessive Power Steering Pipe (8.4.1 (a) (i))**Advice** Wipers slightly smearing**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn To 2mm (5.2.3 (e))**MAJOR** Battery insecure and likely to fall from carrier (4.13 (a) (ii))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**MAJOR** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush Peeling/Seperating From Housing (5.3.4 (a) (i))**Advice** Nearside Outer Sill Damaged**MOT #20**

2020-08-06 13:50

**MOT test number**

565312312347

**Result**

✓ Passed

**MOT #19** 2020-08-03 15:45**MOT test number** 245902914767**Result** ✗ Failed

- MAJOR** Central Exhaust system insecure (6.1.2 (a))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- MAJOR** Central Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

**MOT #18** 2019-07-12 14:36**MOT test number** 205903987139**Result** ✓ Passed

- Advice** Exhaust corroded
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #17** 2019-07-12 10:19**MOT test number** 615556928447**Result** ✗ Failed

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- DANGEROUS** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Exhaust corroded
- DANGEROUS** Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- DANGEROUS** Offside Front Tyre has ply or cords exposed sidewall (5.2.3 (d) (ii))

**MOT #16** 2018-06-29 14:58**MOT test number** 757749490547**Result** ✓ Passed

- Advice** Exhaust rear box outer skin corroded,
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** High vis brake light not working
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #15** 2018-06-29 12:01**MOT test number** 920447709095**Result** ✗ Failed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust rear box outer skin corroded,
- MAJOR** Driver's view of the road through the swept area of the windscreen materially affected by an obstruction items on interior mirror (3.1 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** High vis brake light not working
- MAJOR** Nearside Windscreen wiper not working (3.4 (a))
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #14** 2017-03-10 09:46**MOT test number** 100599330866**Result** ✓ Passed

**MOT #13** 2017-03-04 15:17**MOT test number** 250867087283**Result** ✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Offside Rear Subframe mounting prescribed area is excessively corroded sill (2.4.A.3)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Fail** Nearside Rear Subframe mounting prescribed area is excessively corroded sill (2.4.A.3)
- Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)

**MOT #12** 2016-02-27 08:31**MOT test number** 709592902098**Result** ✓ Passed

- Advice** N/S/R BRAKE PADS GETTING LOW
- Advice** BOTH REAR TYRES SHOWING WEAR

**MOT #11** 2015-03-07 08:26**MOT test number** 949686565017**Result** ✓ Passed**MOT #10** 2014-03-11 15:27**MOT test number** 627560674063**Result** ✓ Passed**MOT #9** 2013-02-14 12:12**MOT test number** 996715043037**Result** ✗ Failed

- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #8** 2013-02-14 12:12**MOT test number** 336615243034**Result** ✓ Passed**MOT #7** 2012-03-06 14:45**MOT test number** 696856262077**Result** ✓ Passed

- Notice** N/s/f headlamp aim only just in limits
- Notice** Front brake discs corroding on inner face
- Notice** Exhaust centre bracket snapped but still secure
- Notice** Rear brake discs slightly worn
- Notice** Front wipers slow to clear screen
- Notice** Exhaust centre & rear box corroding
- Notice** N/s/r tyre deteriorating badly on side walls

**MOT #6** 2011-03-11 15:16**MOT test number** 807520871028**Result** ✓ Passed**MOT #5** 2011-03-10 14:37**MOT test number** 347459261047**Result** ✗ Failed

- Fail** Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
- Fail** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

**MOT #4** 2010-11-13 12:12**MOT test number** 680457010368**Result** ✓ Passed



**MOT #3** 2009-11-27 16:51**MOT test number** 823821939368**Result** ✓ Passed**MOT #2** 2009-09-17 12:24**MOT test number** 324850969442**Result** ✓ Passed**Notice** Centre Exhaust section mountain broken but still secure.**MOT #1** 2009-09-17 10:26**MOT test number** 843440469255**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Centre Exhaust section mountain broken but still secure.



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
16 March 2025

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	16 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>FL56WTE</b>
Plate since	2024-03-29
Current registration	 <b>FL56WTE</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	27
First mileage registration	2006-09-23
Last registration	2024-03-12
Complete history	<a href="#">See info</a>



Registration #1	2006-09-23	22 mi
Registration #2	2009-09-17	31.460 mi
Registration #3	2009-09-17	31.460 mi
Registration #4	2009-11-27	32.910 mi
Registration #5	2010-11-13	30.085 mi
Registration #6	2011-03-10	40.408 mi
Registration #7	2011-03-11	40.408 mi
Registration #8	2012-03-06	44.110 mi
Registration #9	2013-02-14	42.287 mi
Registration #10	2014-03-11	51.398 mi
Registration #11	2015-03-07	57.027 mi
Registration #12	2016-02-27	62.757 mi
Registration #13	2017-03-04	69.643 mi
Registration #14	2017-03-10	69.643 mi
Registration #15	2018-03-09	75.377 mi
Registration #16	2018-03-09	75.377 mi
Registration #17	2018-03-09	75.377 mi
Registration #18	2018-03-09	75.377 mi
Registration #19	2018-03-09	75.377 mi
Registration #20	2018-03-09	75.377 mi
Registration #21	2018-03-09	75.377 mi
Registration #22	2018-03-09	75.377 mi
Registration #23	2018-03-09	75.377 mi
Registration #24	2018-03-09	75.377 mi
Registration #25	2018-03-09	75.377 mi
Registration #26	2018-03-09	75.377 mi

More info >





Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2515 mm
Kerb weight	1285 kg
Max. allowed weight	1650 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	4
Number of axles	2
Engine number	BCA 463754