





General information

Make	AUDI
Model	A8 TDI QUATTRO SPORT
Colour	Blue
Year of manufacture	2005
Top speed	150 mph
0 - 60 mph	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	233 BHP
Max. torque	450 Nm at 1.400 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	32.1 mpg
CO2 emission	231 g/km
CO2 label	L







Internet history

Entry 1

Date Pictures 2021-06-12

16

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-04-26
MOT pass rate	80 %
MOT passed	16
Failed MOT tests	4
Total advice items	20
Total items failed	7

MOT #20	2023-04-27 10:50
MOT test number	151782882321
Result	✓ Passed
Next expiry date	2024-04-26

MOT #19		2022-04-04 13:18
MOT test	number	709261232097
Result		✓ Passed
Minor	Offside Rear Stop lamp(s) with a multiple light source up to 1/2 not fun	actioning (4.3.1 (a) (i))

MOT #18	2022-04-01 08:10
MOT test number	767585746643
Result	🗙 Failed
Fail Offside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))	
FailBrake performance not tested (1.2.1 (g))	

MOT #17	2021-03-16 09:50
MOT test number	775972090219
Result	✓ Passed





MOT #16	2020-03-18 09:58
MOT test number	157784662675
Result	✓ Passed
Advice Offside Front Upper Suspension arm pin or bush worn but not resulting in Front and rear bushes worn (5.3.4 (a) (i))	excessive movement
Advice Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement Front and rear bushes worn (5.3.4 (a) (i))	
MOT #15	2019-03-05 10:25
MOT test number	851132558523
Result	✓ Passed
MOT #14	2018-03-29 11:54
MOT test number	826529949475
Result	✓ Passed
Advice Front brake discs worn/lipped	
Advice Engine covers & under trays fitted	

MOT #13	2018-03-24 10:54
MOT test number	656693268944
Result	🗙 Failed
Advice Front brake discs worn/lipped	
Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A	' Large crack (8.3.1a)
Advice Engine covers & under trays fitted	
Fail Windscreen has damage to the swept area in excess of a 40mm circle outside (8.3.1d)	e zone 'A' Large crack





MOT #12	2017-02-27 16:28
MOT test number	975921533754
Result	✓ Passed
AdviceFront Tyre worn close to the legal limit Both (4.1.E.1)AdviceRear Brake pad(s) wearing thin (3.5.1g)	

MOT #11		2016-03-09 12:36
MOT test	number	246251105079
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #10	2015-01-29 09:27
MOT test number	597949425060
Result	✓ Passed

MOT #9	2014-02-08 10:19
MOT test number	568019334078
Result	✓ Passed

MOT #8	2013-02-16 09:42
MOT test number	178797143098
Result	✓ Passed
Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)	





MOT #7	2012-02-04 10:14
MOT test number	926465332011
Result	Passed
Advice Offside Rear Rear position lamp(s) has light sources not illuminating, (1.1.A.3b)	but not more than 50%
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #6	2011-02-08 14:57
MOT test number	176589231404
Result	✓ Passed

МОТ #5	2010-02-12 15:31
MOT test number	640003140019
Result	✓ Passed

МОТ #4	2010-01-16 10:32	
MOT test number	931796210028	
Result	🗙 Failed	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)		
Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)		

MOT #3	2009-01-10 11:07
MOT test number	594480719070
Result	✓ Passed





MOT #2	2008-02-08 15:14
MOT test number	912819938064
Result	✓ Passed
Advice Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
Advice Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	

MOT #1	2008-02-06 14:57
MOT test number	590027638091
Result	🗙 Failed
Fail Nearside Side repeater missing (1.4.A.2b)	
Advice Offside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	
Advice Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)	



Tax & MOT check

✓ Taxed Tax due: 1 January 2025	X MOT Expired: 26 April 2024
Tax status	Valid until 1 January
Days left	246
MOT expiry date	26 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	e et a
Date	*
Category	AMP
Туре	

Extra AUDI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-05-09
Last registration	2023-04-27
Complete history	See info



Registration #1	2005-05-09	14 mi
Registration #2	2008-02-06	44.797 mi
Registration #3	2008-02-08	44.797 mi
Registration #4	2009-01-10	48.563 mi
Registration #5	2010-01-16	51.197 mi
Registration #6	2010-02-12	51.351 mi
Registration #7	2011-02-08	54.241 mi
Registration #8	2012-02-04	56.727 mi
Registration #9	2013-02-16	58.701 mi
Registration #10	2014-02-08	61.435 mi
Registration #11	2015-01-29	63.117 mi
Registration #12		11.777 mi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 esi
Registration #17		11.777 mi
Registration #18		11.777 esi
Registration #19		11.777 mi
Registration #20		11.777 mi
Registration #21		11.777 mi
Registration #22		11.777 esi





Car features

S0225	Air conditionin
60295	
60482	
0501	
0566	
0567	
0569	

Dimensions & weight

Width	1894 mm
Height	1455 mm
Length	5192 mm
Wheel base	2944 mm
Max. allowed weight	2430 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	ASB 012796