



LS56P JU

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO E (64BHP)
Colour	Blue
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	112 Nm at 3.000 rpm
Cylinders	3
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	55.4 mpg
Consumption combined	47.1 mpg




LABEL UNKNOWN



Internet history

Entry 2

Date	2023-01-09
Pictures	8
Listing price	View report



source: autotrader.co.uk

**MOT history****MOT #17**

2023-04-11 12:07

MOT test number

536803454880

Result**✗ Failed**

Fail Nearside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Suspension arm damaged and seriously weakened (5.3.3 (b) (i))

Fail Exhaust emissions - engine idle speed too high (8.2.1.2 (e))

MOT #16

2022-02-21 17:14

MOT test number

319208574986

Result**✓ Passed**

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. offside rear brake working bit late (1.2.1 (b) (i))

MOT #15

2021-02-22 17:18

MOT test number

632186042590

Result**✓ Passed****MOT #14**

2019-05-28 15:40

MOT test number

822247553143

Result**✓ Passed**

**MOT #13** 2018-06-12 09:28**MOT test number** 993668647624**Result** ✓ Passed**MOT #12** 2017-12-29 16:12**MOT test number** 402250965229**Result** ✓ Passed**Advice** Engine covers and under trays fitted obscuring some components**MOT #11** 2017-12-29 16:12**MOT test number** 462943487986**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Engine covers and under trays fitted obscuring some components**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #10** 2016-12-13 11:55**MOT test number** 524852828507**Result** ✓ Passed**Advice** Engine covers fitted obscuring some components**Advice** Central Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Under trays fitted obscuring some components

**MOT #9** 2016-01-05 18:00**MOT test number** 112245445756**Result** ✓ Passed**Advice** Under trays fitted obscuring some componenets**Advice** Engine covers fitted obscuring saome componenets**Advice** Nearside Rear nail in tyre**MOT #8** 2016-01-04 13:59**MOT test number** 313559847458**Result** ✗ Failed**Advice** Nearside Rear nail in tyre**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Under trays fitted obscuring some componenets**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Engine covers fitted obscuring saome componenets**MOT #7** 2014-12-23 09:32**MOT test number** 477667454408**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #6** 2014-01-03 10:33**MOT test number** 157143104031**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2012-12-27 10:38**MOT test number** 918092062391**Result** ✓ Passed**MOT #4** 2011-12-15 11:04**MOT test number** 749879341372**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #3** 2010-12-14 14:22**MOT test number** 812858240336**Result** ✓ Passed**MOT #2** 2009-12-29 16:28**MOT test number** 400733469347**Result** ✓ Passed**MOT #1** 2009-12-29 14:57**MOT test number** 322513669300**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LS56PJU
Plate since	2019-06-29
Current registration	 LS56PJU
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-01-05
Last registration	2023-04-11
Complete history	See info



Registration #1	2007-01-05	16 mi
Registration #2	2009-12-29	18.643 mi
Registration #3	2009-12-29	18.643 mi
Registration #4	2010-12-14	24.662 mi
Registration #5	2011-12-15	30.361 mi
Registration #6	2012-12-27	36.197 mi
Registration #7	2014-01-03	41.510 mi
Registration #8	2014-12-23	46.201 mi
Registration #9	2016-01-04	51.084 mi
Registration #10	2016-01-05	51.084 mi
Registration #11	2016-01-05	51.084 mi
Registration #12	2016-01-05	51.084 mi
Registration #13	2016-01-05	51.084 mi
Registration #14	2016-01-05	51.084 mi
Registration #15	2016-01-05	51.084 mi
Registration #16	2016-01-05	51.084 mi
Registration #17	2016-01-05	51.084 mi
Registration #18	2016-01-05	51.084 mi
Registration #19	2016-01-05	51.084 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1650 mm
Height	1467 mm
Length	3916 mm
Wheel base	2466 mm
Kerb weight	1194 kg
Max. allowed weight	1570 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3

Number of seats	5
Number of axles	2
Engine number	BME244263