






report date: 2024-03-29

## General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	White
Year of manufacture	2010
Top speed	155 mph
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	196 g/km
CO2 label	J



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history


#### Entry 2

Date 2023-12-02

Pictures 13

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-08-06

Pictures 44

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

#### **MOT** history

MOT expiry date	2024-12-04
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	10
Total items failed	1

MOT #14	2023-12-05 11:43
MOT test number	351999659514
Result	✓ Passed
Next expiry date	2024-12-04

2023-05-19 15:38
556875924157
✓ Passed

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement frontmost (5.3.4 (a) (i))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement frontmost (5.3.4 (a) (i))

**MOT #12** 2023-05-19 10:12

MOT test number 507869442386

Result X Failed

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement frontmost (5.3.4 (a) (i))

**MAJOR** Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))

**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement frontmost (5.3.4 (a) (i))

MAJOR Nearside Front Upper Shock absorbers insecurely attached (5.3.2 (a) (i))

CarCheck.co.uk page 3/12



Fail

**MA10YHY** 

report date: 2024-03-29

MOT #11	2022-05-17 08:15
MOT test number	878297399936
Result	✓ Passed
MOT #10	2021-04-30 16:14
MOT test number	204059991667
Result	✓ Passed
MOT #9	2020-05-20 13:25
MOT test number	386864515365
Result	✓ Passed
MOT #8	2019-05-28 14:42
MOT test number	712533833171
Result	<b>✓</b> Passed
MOT #7	2018-05-11 14:39
MOT test number	899700831315
Result	<b>✓</b> Passed
MOT #6	2018-05-11 09:12
MOT test number	280738420921
Result	<b>×</b> Failed

MOT #5	2017-05-09 15:31
MOT test number	366524199735
Result	<b>✓</b> Passed

Nearside Front Lower Front suspension has excessive movement at a suspension ball joint (2.5.A.1c)

CarCheck.co.uk page 4/12



MOT #4 2016-05-12 14:17

**MOT test number** 518745511762

**Advice** Nearside Rear Tyre worn close to the legal limit 245/35R18 y xl (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit 245/35R18 y xl (4.1.E.1)

MOT #3 2015-04-02 13:18

MOT test number 157642895087

**Result** ✓ Passed

MOT #2 2014-03-31 08:12

**MOT test number** 186960294485

Result \rightarrow Passed

MOT #1 2013-04-10 10:43

**MOT test number** 277720603170

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 December
Days left	216
MOT expiry date	4 December 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-29


## Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



#### Extra MERCEDES salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

# Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	
***************************************	
Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

## Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courte et info	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-04-12
Last registration	2023-12-05
Complete history	See info



Registration #1	2010-04-12	8 mi
Registration #2	2013-04-10	23.128 mi
Registration #3	2014-03-31	22.310 mi
Registration #4	2015-04-02	30.025 mi
Registration #5	2016-05-12	39.908 mi
Registration #6	2017-05-09	47.435 mi
Registration #7	2018-05-11	54.477 mi
Registration #8	2018-05-11	54.477 mi
Registration #9	2019-05-28	62.544 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.70 es

More info >

CarCheck.co.uk page 11/12



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1415 kg
Max. allowed weight	1705 kg

# Additional information

Fuel tank capacity	70
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431331085

CarCheck.co.uk page 12/12