



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MOKKA DESIGN NAV ECOTEC S/S
Colour	Orange
Year of manufacture	2018
Top speed	122 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.900 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.8 mpg
CO2 emission	150 g/km
CO2 label	F






Internet history

Entry 3



Date	2022-02-25
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 2

Date	2021-12-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

Entry 1

Date	2021-11-24
Pictures	0
Listing price	View report

source: [heyicar.co.uk](#)



MOT history

MOT expiry date	2025-01-25
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	5

MOT #6	2024-01-26 14:28
MOT test number	937961903593
Result	✓ Passed
Next expiry date	2025-01-25
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5	2024-01-19 17:15
MOT test number	273535679401
Result	✗ Failed
Fail	Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #4	2023-01-13 10:37
MOT test number	972539363322
Result	✓ Passed

**MOT #3** 2022-11-25 15:27**MOT test number** 432221183079**Result** ✗ Failed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**MOT #2** 2021-11-17 09:11**MOT test number** 846622279659**Result** ✓ Passed**MOT #1** 2021-08-28 09:54**MOT test number** 479592129600**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	DV68EAY
Plate since	2019-06-29
Current registration	DV68EAY
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-09-17
Last registration	2024-01-26
Complete history	See info



Registration #1	2018-09-17	15 mi
Registration #2	2021-08-28	42.514 mi
Registration #3	2021-11-17	44.057 mi
Registration #4	2022-05-20	45.277 mi
Registration #5	2022-05-20	45.277 mi
Registration #6	2022-05-20	45.277 mi
Registration #7	2022-05-20	45.277 mi
Registration #8	2022-05-20	45.277 mi
Registration #9	2022-05-20	45.277 mi
Registration #10	2022-05-20	45.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2038 mm
Height	1658 mm
Length	4275 mm
Wheel base	2555 mm
Kerb weight	1319 kg
Max. allowed weight	1828 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	B14NET 182930672LUJ