



HONDA




report date: 2023-12-01

General information

Make	HONDA
Model	JAZZ DSI S
Colour	Blue
Year of manufacture	2009
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	76 BHP
Max. torque	110 Nm at 2.800 rpm
Engine capacity	1.246 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





MOT history

MOT expiry date	2024-12-13
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	17
Total items failed	2

MOT #14 2023-12-14 09:08

MOT test number 990396959720

Result ✓ Passed

Next expiry date 2024-12-13

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13 2022-11-23 10:58

MOT test number 935429950060

Result ✓ Passed

Minor Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #12 2021-12-05 11:04

MOT test number 408183743862

Result ✓ Passed

Minor Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

Minor Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))



MOT #11 2020-11-21 12:04

MOT test number 333936133871

Result ✓ Passed

Advice Front Lower Suspension arm pin or bush worn but not resulting in excessive movement both sides (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10 2019-04-25 15:25

MOT test number 280642334701

Result ✓ Passed

Minor Offside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

MOT #9 2018-02-09 09:48

MOT test number 686526479519

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Central Rear Upper high level brake light not working

MOT #8 2018-02-08 14:37

MOT test number 422989154963

Result ✗ Failed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Central Rear Upper high level brake light not working

MOT #7 2017-02-06 15:26

MOT test number 385343771593

Result ✓ Passed

Advice Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)



MOT #6	2017-02-06 15:26
MOT test number	668712370011
Result	✗ Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)
Advice	Nearside Front Outer Tyre worn close to the legal limit (4.1.E.1)

MOT #5	2016-01-29 10:05
MOT test number	597520973849
Result	✓ Passed

MOT #4	2015-01-27 11:50
MOT test number	838297625046
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3	2014-01-22 12:03
MOT test number	579542824071
Result	✓ Passed

MOT #2	2013-01-14 11:24
MOT test number	135844613438
Result	✓ Passed

MOT #1	2012-01-12 16:28
MOT test number	762383051809
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 October 2024

✓
MOT

Expires:
13 December 2024

Tax status Valid until 1 October

Days left 218

MOT expiry date 13 December 2024

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-




Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	RA58AWC
Plate since	2019-09-29
Current registration	RA58AWC
Plate since	2019-09-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled. If not, and you buy this HONDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this HONDA is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-01-29
Last registration	2023-12-14
Complete history	See info



Registration #1	2009-01-29	7 mi
Registration #2	2012-01-12	13.218 mi
Registration #3	2013-01-14	18.631 mi
Registration #4	2014-01-22	24.457 mi
Registration #5	2015-01-27	29.688 mi
Registration #6	2016-01-29	34.936 mi
Registration #7	2017-02-06	48.276 mi
Registration #8	2017-02-06	48.276 mi
Registration #9	2019-05-01	55.277 mi
Registration #10	2019-05-01	55.277 mi
Registration #11	2019-05-01	55.277 mi
Registration #12	2019-05-01	55.277 mi
Registration #13	2019-05-01	55.277 mi
Registration #14	2019-05-01	55.277 mi
Registration #15	2019-05-01	55.277 mi

[More info >](#)



Safety ratings

NCAP rating ★★★★☆
Video [see crash video](#)



Dimensions & weight

Width	1675 mm
Height	1525 mm
Length	3845 mm
Wheel base	2450 mm
Kerb weight	1086 kg
Max. allowed weight	1490 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L12A17002423