





report date: 2024-03-28

General information

Make	FORD
Model	FIESTA TITANIUM
Colour	Red
Year of manufacture	2010
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	128 Nm at 4.200 rpm
Engine capacity	1.388 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	133 g/km
CO2 label	E



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 2

Date 2023-02-20

Pictures 12

Listing price <u>View report</u>










source: autotrader.co.uk

Entry 1

Date	2021-01-30	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-05-03
MOT pass rate	65 %
MOT passed	11
Failed MOT tests	6
Total advice items	10
Total items failed	8

MOT #17	2024-04-15 14:43
MOT test number	877086914697
Result	✓ Passed
Next expiry date	2025-05-03
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #16	2023-04-12 15:37
MOT test number	321689948709
Result	✓ Passed

MOT #	15 20	23-04-12 11:14
MOT te	est number	992638765007
Result		🗙 Failed
Fail	Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn OS&NS (5.1.2	? (b) (i))
Fail	Front Suspension arm ball joint excessively worn OS&NS (5.3.4 (a) (i))	

MOT #14	2022-05-03 12:12
MOT test number	415703869335
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

× Failed

MOT #13 2021-05-04 11:40

MOT test number 120447578587

MOT #12 2021-04-29 10:43

MOT test number 177153783929

Result ★ Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #11 2021-04-29 09:46

MOT test number 545535137435

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #10 ______2019-09-27 08:21

MOT test number 964399892881

Result ✓ Passed

MOT #9 2019-09-27 08:21

MOT test number 227865684592

Result X Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

204410439423

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge tread cracking (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge tread cracking (5.2.3 (e))

MOT test number

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge tread cracking (5.2.3 (e))

Pass with rectification Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge tread cracking (5.2.3 (e))

d cracking (5.2.3 (e))
2017-09-18 11:08
737030454254
✓ Passed
2016-10-03 10:52
963970976730
✓ Passed
2015-10-01 14:59
133093399822
✓ Passed
2014-10-08 09:18

MOT #3	2014-10-08 09:18
MOT test number	307961784227
Result	✓ Passed
Advice Steering system has slight free play detected at steering wheel (2.2.A.1b)	

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #2 2013-10-09 12:11

MOT test number 368432683225

Result ✓ Passed

MOT #1 2013-10-08 13:56

MOT test number 286201283217

Result X Failed

Fail Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 May
Days left	2
MOT expiry date	3 May 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category



Extra FORD salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

THE STATE OF THE S	
THE STREET STREE	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-09-22
Last registration	2024-04-15
Complete history	See info



Registration #1	2010-09-22	17 mi
Registration #2	2013-10-08	22.005 mi
Registration #3	2013-10-09	22.005 mi
Registration #4	2014-10-08	30.031 mi
Registration #5	2015-10-01	36.534 mi
Registration #6	2016-10-03	43.527 mi
Registration #7	2017-09-18	50.549 mi
Registration #8	2018-09-22	58.515 mi
Registration #9	2018-09-22	58.515 mi
Registration #10	2019-09-27	71.028 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		71.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Wheel base	2489 mm
Kerb weight	1041 kg
Max. allowed weight	1495 kg

Additional information

Fuel tank capacity	42 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page 1	.3/13

Number of axles 2

Engine number 9E63133