



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK350 ELEGANCE
Colour	Silver
Year of manufacture	2009
Top speed	155 mph
0 - 60 mph	6.7 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	268 BHP
Max. torque	350 Nm at 3.000 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	19.3 mpg
Consumption extra urban	36.7 mpg
Consumption combined	27.7 mpg
CO2 emission	241 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-10-10
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-09-16
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	13
Total items failed	2

MOT #13	2022-09-17 08:09
MOT test number	939530515345
Result	✓ Passed
Next expiry date	2023-09-16
Advice	Under tray fitted

MOT #12	2021-05-11 08:41
MOT test number	631673668686
Result	✓ Passed

MOT #11	2020-05-18 12:31
MOT test number	806523435934
Result	✓ Passed

MOT #10	2019-05-13 07:55
MOT test number	231837613985
Result	✓ Passed

MOT #9	2018-05-18 08:23
MOT test number	457918892948
Result	✓ Passed

**MOT #8** 2017-06-08 10:51**MOT test number** 419876183357**Result** ✓ Passed**MOT #7** 2016-07-27 10:02**MOT test number** 172413700120**Result** ✓ Passed**MOT #6** 2015-07-27 12:31**MOT test number** 947208705299**Result** ✓ Passed

- Notice** Nail in offside rear tyre
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Advice** Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #5 2014-07-16 15:21**MOT test number** 238117394495**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2014-07-16 10:13**MOT test number** 138237694146**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #3	2013-07-15 13:58
MOT test number	485446793170
Result	✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components

MOT #2	2013-07-15 10:26
MOT test number	488776693192
Result	✗ Failed
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Notice	Under-trays fitted obscuring some underside components
Fail	Brakes imbalanced across an axle (3.7.B.5b)

MOT #1	2012-07-19 11:03
MOT test number	225531502201
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
30 September 2023

✕
MOT

Expired:
16 September 2023

Tax status	Expired at 30 September
Days left	213 days too late
MOT expiry date	16 September 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 KS09MGU
Plate since	2019-03-29
Current registration	 KS09MGU
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-07-29
Last registration	2022-09-17
Complete history	See info



Registration #1	2009-07-29	29 mi
Registration #2	2012-07-19	26.371 mi
Registration #3	2013-07-15	35.288 mi
Registration #4	2013-07-15	35.291 mi
Registration #5	2014-07-16	38.669 mi
Registration #6	2014-07-16	38.671 mi
Registration #7	2015-07-27	42.294 mi
Registration #8	2016-07-27	46.040 mi
Registration #9	2016-07-27	46.040 mi
Registration #10	2016-07-27	46.040 mi
Registration #11	2016-07-27	46.040 mi
Registration #12	2016-07-27	46.040 mi
Registration #13	2016-07-27	46.040 mi
Registration #14	2016-07-27	46.040 mi
Registration #15	2016-07-27	46.040 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2690 mm
Kerb weight	1735 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27296030984936