



RENAULT

KL06WHS

report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC DYNAMIQUE VVT 111 SCENIC EU4
Colour	Purple
Year of manufacture	-
Top speed	109 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-03
Pictures	7
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history****MOT #17** 2021-01-25 14:14**MOT test number** 583513094244**Result** ✓ Passed**Next expiry date** 2022-01-24**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))**MOT #16** 2020-03-19 11:08**MOT test number** 494715538633**Result** ✓ Passed**MOT #15** 2019-06-03 13:48**MOT test number** 749645573497**Result** ✓ Passed**Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Rear shock absorber slightly corroded**Advice** Offside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Advice** Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear shock absorber slightly corroded**Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

**MOT #14**

2018-06-01 07:54

MOT test number

628463641363

Result

✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13**

2018-06-01 07:54

MOT test number

615149961172

Result

✗ Failed

Pass with rectification Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12**

2017-05-24 13:59

MOT test number

503383323576

Result

✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened both (3.5.1i)**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)**Advice** Rear Brake hose has slight corrosion to ferrules both (3.6.B.4e)**MOT #11**

2016-06-03 11:11

MOT test number

413314311328

Result

✓ Passed

**MOT #10** 2015-05-22 10:40**MOT test number** 355402545100**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #9** 2015-05-22 10:40**MOT test number** 246722145485**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2014-06-02 11:15**MOT test number** 426303354172**Result** ✓ Passed**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2014-06-02 11:15**MOT test number** 997383754184**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Rear Direction indicators incorrect colour (1.4.A.2f)**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**MOT #6** 2013-06-03 12:22**MOT test number** 387474353101**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-05-28 14:06**MOT test number** 589519442104**Result** ✓ Passed**MOT #4** 2011-03-29 10:30**MOT test number** 139148981071**Result** ✓ Passed**MOT #3** 2010-03-30 10:36**MOT test number** 534509280071**Result** ✓ Passed



MOT #2	2009-02-24 09:46
MOT test number	224635159027
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2009-02-24 09:46
MOT test number	313865559005
Result	✗ Failed
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	KL06WHS
Plate since	2019-09-28
Current registration	KL06WHS
Plate since	2019-09-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-03-30
Last registration	2021-01-25
Complete history	See info



Registration #1	2006-03-30	28 mi
Registration #2	2009-02-24	21.755 mi
Registration #3	2010-03-30	27.516 mi
Registration #4	2011-03-29	31.824 mi
Registration #5	2012-05-28	38.345 mi
Registration #6	2013-06-03	46.547 mi
Registration #7	2014-06-02	54.103 mi
Registration #8	2015-05-22	62.948 mi
Registration #9	2016-05-22	71.793 mi
Registration #10	2017-05-22	80.638 mi
Registration #11	2018-05-22	89.483 mi
Registration #12	2019-05-22	98.328 mi
Registration #13	2020-05-22	107.173 mi
Registration #14	2021-05-22	116.018 mi
Registration #15	2022-05-22	124.863 mi
Registration #16	2023-05-22	133.708 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1810 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1370 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D004703