




report date: 2024-03-29

General information

Make	KIA
Model	CARENS LS CRDI
Colour	Silver
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	12.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	138 BHP
Max. torque	305 Nm at 2.500 rpm
Engine capacity	1.991 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-06-04
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-27
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	38
Total items failed	22

MOT #20	2024-04-26 08:47
MOT test number	583284812449
Result	✓ Passed
Next expiry date	2025-04-27

MOT #19	2023-04-20 14:50
MOT test number	563753055955
Result	✓ Passed
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Suspension components corroded
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #18**

2023-04-19 09:56

MOT test number

279496993837

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Fail** Service brake efficiency below requirements (1.2.2 (a) (i))
- Fail** Front Brakes imbalanced across an axle by more than 50% Axle 1 (1.2.1 (b) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Suspension components corroded
- Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Fail** Offside Rear Brake pipe leaking on a hydraulic braking system Pipe burst during brake test (1.1.11 (b) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))

**MOT #17**

2022-04-28 07:24

MOT test number

135431958821

Result

✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #16**

2022-04-07 14:44

MOT test number

521022516778

Result

✗ Failed

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Fail** Nearside Front Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #15**

2021-03-23 15:17

MOT test number

428151365168

Result

✓ Passed

**MOT #14** 2021-03-23 11:15**MOT test number** 360535154956**Result** ✗ Failed**Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MOT #13** 2020-03-24 16:56**MOT test number** 574193421996**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Tyre worn close to legal limit/worn on edge both front tyres inner edge (5.2.3 (e))**MOT #12** 2020-03-24 16:56**MOT test number** 112871362241**Result** ✗ Failed**Advice** Front Tyre worn close to legal limit/worn on edge both front tyres inner edge (5.2.3 (e))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #11** 2019-04-05 10:01**MOT test number** 829383839913**Result** ✓ Passed**MOT #10** 2018-04-04 13:00**MOT test number** 307577202687**Result** ✓ Passed

**MOT #9** 2017-04-08 12:33**MOT test number** 129834147797**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (3.5.1i)**MOT #8** 2017-04-04 06:50**MOT test number** 687452138019**Result** ✗ Failed**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**Advice** Brake disc worn, pitted or scored, but not seriously weakened both rear (3.5.1i)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #7** 2016-08-12 08:51**MOT test number** 219491078160**Result** ✓ Passed**Advice** Nearside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #6** 2015-08-18 00:00**MOT test number** 359692324124**Result** ✓ Passed**MOT #5** 2014-08-04 13:50**MOT test number** 566806914276**Result** ✓ Passed

**MOT #4** 2013-08-02 11:35**MOT test number** 129554013219**Result** ✓ Passed**MOT #3** 2012-08-10 12:48**MOT test number** 618593722267**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2011-08-05 09:05**MOT test number** 998607711204**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2011-08-04 16:15**MOT test number** 616646811221**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
27 April 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	27 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history


Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	LA08KYO
Plate since	2019-03-29
Current registration	LA08KYO
Plate since	2019-03-29

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-08-18
Last registration	2024-04-26
Complete history	See info



Registration #1	2008-08-18	6 mi
Registration #2	2011-08-04	21.464 mi
Registration #3	2011-08-05	21.464 mi
Registration #4	2012-08-10	32.207 mi
Registration #5	2013-08-02	42.417 mi
Registration #6	2014-08-04	52.078 mi
Registration #7	2015-08-18	64.504 mi
Registration #8	2016-08-12	78.532 mi
Registration #9	2017-04-04	86.466 mi
Registration #10	2017-04-08	86.467 mi
Registration #11	2018-04-04	89.615 mi
Registration #12	2019-04-04	92.763 mi
Registration #13	2020-04-04	95.911 mi
Registration #14	2021-04-04	99.059 mi
Registration #15	2022-04-04	102.207 mi
Registration #16	2023-04-04	105.355 mi
Registration #17	2024-04-26	108.503 mi
Registration #18		
Registration #19		
Registration #20		
Registration #21		
Registration #22		

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1720 mm
Length	4545 mm
Wheel base	2700 mm
Kerb weight	1681 kg
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4EA8H374231