



WP590YR

report date: 2024-03-28

General information

Make	FIAT
Model	DUCATO 35 LWB DCC MJ 120
Colour	White
Year of manufacture	2009
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.287 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-07
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-18
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	34
Total items failed	14

MOT #15	2023-05-13 09:23
MOT test number	658433391406
Result	✓ Passed
Next expiry date	2024-05-18

MOT #14	2022-05-07 09:42
MOT test number	791124823854
Result	✓ Passed
Advice	Exhaust silencer outer casing deteriorated

MOT #13	2022-05-07 07:44
MOT test number	386771458214
Result	✗ Failed
Fail	Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Exhaust silencer outer casing deteriorated
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #12** 2021-05-15 08:20**MOT test number** 482984370098**Result** ✓ Passed**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside (rear bushes) (5.3.4 (a) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #11** 2021-05-08 08:34**MOT test number** 778067649592**Result** ✗ Failed**Fail** Offside Rear Leaf spring shackle pin or bush excessively worn rear bush (5.3.4 (a) (i))**Fail** Nearside Rear Leaf spring shackle pin or bush excessively worn rear bush (5.3.4 (a) (i))**Advice** Front Lower Suspension arm pin or bush worn but not resulting in excessive movement offside and nearside (rear bushes) (5.3.4 (a) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #10** 2020-05-19 16:46**MOT test number** 497408545567**Result** ✓ Passed**Advice** Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #9** 2019-03-19 13:59**MOT test number** 774114624981**Result** ✓ Passed**MOT #8** 2019-03-19 13:59**MOT test number** 105585401847**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))



MOT #7

2018-03-19 17:08

MOT test number

485001525998

Result

✓ Passed

- Advice
- Offside headlight lense misted up but not affecting beam pattern
- Advice
- Nearside Front brake pad sensor wire broken
- Advice
- Oil leak sump and oil filter

MOT #6

2015-10-22 08:44

MOT test number

467396620627

Result

✓ Passed

- Advice
- Both rear tyres worn on edges
- Advice
- Parking brake lever has little reserve travel (3.1.6b)
- Advice
- Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice
- N/s/r lamp unit damaged
- Advice
- Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice
- Both door mirrors damaged

**MOT #5** 2015-10-21 15:56**MOT test number** 769195931772**Result** ✗ Failed

- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Both door mirrors damaged
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Both rear tyres worn on edges
- Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Electrical wiring insecure n/s/f brake pad warning wire (1.9.2a)
- Fail** Registration plate lamp not working both (1.1.C.1d)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** N/s/r lamp unit damaged
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front Lower Suspension arm rubber bush bonding deteriorated resulting in excessive movement both sides (2.4.G.2)

MOT #4 2014-10-30 17:23**MOT test number** 458743304424**Result** ✓ Passed

- Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)
- Notice** N/s/f tyre close to legal limit, worn on edges and has nail
- Advice** Side repeater slightly discoloured (1.4.A.2f)
- Notice** Both door mirrors damaged

**MOT #3**

2014-10-29 16:16

MOT test number

629512504378

Result**✗ Failed****Advice** Side repeater slightly discoloured (1.4.A.2f)**Notice** Both door mirrors damaged**Fail** Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Notice** N/s/f tyre close to legal limit, worn on edges and has nail**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #2**

2013-11-01 16:45

MOT test number

197395503361

Result**✓ Passed****Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #1**

2013-10-31 16:13

MOT test number

109044903338

Result**✗ Failed****Advice** Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Fail** Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Shock absorber has a serious fluid leak (2.7.3)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
18 May 2024

Tax status	Valid until 1 May
-------------------	-------------------

Days left	367
------------------	-----

MOT expiry date	18 May 2024
------------------------	-------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-12-23
Last registration	2023-05-13
Complete history	See info



Registration #1	2009-12-23	11 mi
Registration #2	2013-10-31	59.744 mi
Registration #3	2013-11-01	59.744 mi
Registration #4	2014-10-29	80.467 mi
Registration #5	2014-10-30	80.512 mi
Registration #6	2015-10-21	99.723 mi
Registration #7	2015-10-22	99.723 mi
Registration #8	2018-03-19	108.225 mi
Registration #9	2019-03-19	142.960 mi
Registration #10	2020-05-20	151.277 mi
Registration #11	2020-05-20	151.277 mi
Registration #12	2020-05-20	151.277 mi
Registration #13	2020-05-20	151.277 mi
Registration #14	2020-05-20	151.277 mi
Registration #15	2020-05-20	151.277 mi
Registration #16	2020-05-20	151.277 mi
Registration #17	2020-05-20	151.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2050 mm
Kerb weight	1840 kg
Max. allowed weight	3500 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	7
Number of axles	2
Engine number	0714723