



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D5 SPORT V50
Colour	Blue
Year of manufacture	2006
Top speed	138 mph
0 - 60 mph	8.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	177 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	2.401 cc
Cylinders	5
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.4 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-07-29
Pictures	30
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-16
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	32
Total items failed	9

MOT #21	2023-10-17 16:40
MOT test number	948093459151
Result	✓ Passed
Next expiry date	2024-10-16
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #20	2023-09-12 08:59
MOT test number	378995647631
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Offside Front Inner Drive shaft joint constant velocity boot missing (6.1.7 (g) (ii))

**MOT #19**

2022-08-16 11:08

MOT test number

851700176452

Result

✓ Passed

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Offside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #18

2021-08-27 14:49

MOT test number

120719555676

Result

✓ Passed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17

2021-08-27 11:52

MOT test number

853899575179

Result

✗ Failed

- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2020-08-07 08:01

MOT test number

595844916911

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Tyre cracking and starting to wear inner edge (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Tyre worn inner edge (5.2.3 (e))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge Tyre worn inner edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #15

2020-08-07 08:01

MOT test number

783056079849

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge Tyre worn inner edge (5.2.3 (e))

Pass with rectification Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing Tyre cracking and starting to wear inner edge (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge Tyre worn inner edge (5.2.3 (e))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

MOT #14

2019-09-07 08:39

MOT test number

419218040234

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13** 2019-09-04 13:46**MOT test number** 296526369284**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**MOT #12** 2018-08-23 09:11**MOT test number** 449664798962**Result** ✓ Passed**MOT #11** 2017-08-30 10:22**MOT test number** 903888214960**Result** ✓ Passed**MOT #10** 2016-08-13 11:09**MOT test number** 505457409991**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit inner edge (4.1.E.1)**MOT #9** 2015-09-07 10:15**MOT test number** 385405385227**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #8	2014-10-10 12:12
---------------	------------------

MOT test number	485153284224
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2013-10-17 12:08
---------------	------------------

MOT test number	806860293291
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2012-10-04 15:46
---------------	------------------

MOT test number	876798272224
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2012-10-04 11:11
---------------	------------------

MOT test number	287898772228
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
-------------	--

MOT #4	2011-10-03 14:46
---------------	------------------

MOT test number	137116071205
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2010-09-23 14:36
---------------	------------------

MOT test number	364826360262
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2010-09-23 09:51
---------------	------------------

MOT test number	950906460265
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	---

Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)
-------------	--



MOT #1	2009-09-11 14:13
MOT test number	592154159276
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
16 October 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	16 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-10-02
Last registration	2023-10-17
Complete history	See info



Registration #1	2006-10-02	7 mi
Registration #2	2009-09-11	21.166 mi
Registration #3	2010-09-23	29.447 mi
Registration #4	2010-09-23	29.447 mi
Registration #5	2011-10-03	36.936 mi
Registration #6	2012-10-04	43.981 mi
Registration #7	2012-10-04	43.981 mi
Registration #8	2013-10-17	51.699 mi
Registration #9	2014-10-10	60.528 mi
Registration #10	2015-09-07	64.848 mi
Registration #11	2016-08-13	73.389 mi
Registration #12	2017-08-30	80.700 mi
Registration #13	2018-08-30	88.011 mi
Registration #14	2019-08-30	95.322 mi
Registration #15	2020-08-30	102.633 mi
Registration #16	2021-08-30	109.944 mi
Registration #17	2022-08-30	117.255 mi
Registration #18	2023-08-30	124.566 mi
Registration #19	2024-08-30	131.877 mi
Registration #20	2025-08-30	139.188 mi
Registration #21	2026-08-30	146.499 mi
Registration #22	2027-08-30	153.810 mi
Registration #23	2028-08-30	161.121 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4513 mm
Wheel base	2640 mm
Kerb weight	1461 kg
Max. allowed weight	2020 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	409830