



report date: 2024-03-28

## General information

Make	NISSAN
Model	PIXO N-TEC
Colour	Grey
Year of manufacture	2009
Top speed	96 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	103 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-06-22
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-15
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	28
Total items failed	1

MOT #14	2024-02-05 14:13
MOT test number	878440899661
Result	✓ Passed
Next expiry date	2025-02-15
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Fuel Pipe/s corroded
Advice	Brake hose has slight corrosion to ferrule all (1.1.12 (f) (i))

**MOT #13**

2023-02-01 14:45

**MOT test number**

636306798170

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm and worn on edges (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre bald on inner edge close to cords (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #12**

2023-02-01 14:45

**MOT test number**

858352017247

**Result**

✗ Failed

- Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2.5mm and worn on edges (5.2.3 (e))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge Tyre bald on inner edge close to cords (5.2.3 (e))



<b>MOT #11</b>	2022-02-16 15:40
----------------	------------------

<b>MOT test number</b>	939296370570
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #10</b>	2021-06-24 10:31
----------------	------------------

<b>MOT test number</b>	129699151777
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #9</b>	2020-07-03 13:54
---------------	------------------

<b>MOT test number</b>	726689111713
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #8</b>	2019-07-05 13:20
---------------	------------------

<b>MOT test number</b>	995837441730
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #7</b>	2018-07-05 10:39
---------------	------------------

<b>MOT test number</b>	280183236128
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #6</b>	2017-07-05 15:15
---------------	------------------

<b>MOT test number</b>	594190656887
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>Advice</b>	Offside Front Tyre worn close to the legal limit (4.1.E.1)
---------------	--

<b>MOT #5</b>	2016-07-15 07:58
---------------	------------------

<b>MOT test number</b>	152339492318
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------



MOT #4	2015-07-16 12:34
MOT test number	157637095122
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Front brakes worn
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3	2014-07-21 12:50
MOT test number	518642504289
Result	✓ Passed

MOT #2	2013-06-19 10:31
MOT test number	969810273162
Result	✓ Passed

MOT #1	2012-06-21 14:53
MOT test number	138583372165
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Notice	Items removed from driver's view prior to test



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
15 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	337
<b>MOT expiry date</b>	15 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-24
Last registration	2024-02-05
Complete history	<a href="#">See info</a>



Registration #1	2009-06-24	20 mi
Registration #2	2012-06-21	25.508 mi
Registration #3	2013-06-19	32.616 mi
Registration #4	2014-07-21	39.849 mi
Registration #5	2015-07-16	43.030 mi
Registration #6	2016-07-15	45.678 mi
Registration #7	2017-07-05	48.971 mi
Registration #8	2018-07-05	51.925 mi
Registration #9	2019-06-20	55.277 mi
Registration #10	2020-06-19	58.277 mi
Registration #11	2021-06-19	61.277 mi
Registration #12	2022-06-19	64.277 mi
Registration #13	2023-06-19	67.277 mi
Registration #14	2024-02-05	70.277 mi
Registration #15	2024-02-05	70.277 mi
Registration #16	2024-02-05	70.277 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1630 mm
Height	1470 mm
Length	3565 mm
Wheel base	2360 mm
Kerb weight	855 kg
Max. allowed weight	1250 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	107462