



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4 VVTI NV
Colour	Black
Year of manufacture	2002
Top speed	106 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	158 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.2 mpg
CO2 emission	175 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-07-24
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2024-07-29
MOT pass rate	79 %
MOT passed	19
Failed MOT tests	5
Total advice items	29
Total items failed	15

MOT #24	2023-07-10 09:52
MOT test number	133562041577
Result	✓ Passed
Next expiry date	2024-07-29
Advice	Headlamp covers deteriorated

MOT #23	2022-06-30 08:46
MOT test number	619182405004
Result	✓ Passed
Advice	Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

MOT #22	2021-07-30 14:13
MOT test number	776924387982
Result	✓ Passed
Advice	Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	All suspension slightly corroded



MOT #21

2021-07-29 18:47

MOT test number

779485271734

Result

✗ Failed

- Advice

Parking brake has little reserve travel
- Advice

Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail

Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice

All suspension slightly corroded
- Fail

Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #20

2021-03-08 14:41

MOT test number

103063658563

Result

✓ Passed

- Advice

Main chassis and suspension corroded
- Advice

Parking brake travel near limit
- Advice

Brake hose has slight corrosion to ferrule all (1.1.12 (f) (i))

**MOT #19**

2021-03-08 10:35

MOT test number

723489414228

Result**✗ Failed****Fail** Headlamp aim projected beam image is obviously incorrect both (4.1.2 (c))**Fail** Main beam tell-tale not working (4.9.1 (a) (ii))**Fail** Offside Front Brake hose excessively twisted (1.1.12 (b) (ii))**Advice** Parking brake travel near limit**Fail** Nearside Rear Rear reflector missing (4.8.2 (a) (ii))**Advice** Brake hose has slight corrosion to ferrule all (1.1.12 (f) (i))**Advice** Main chassis and suspension corroded**MOT #18**

2020-02-24 09:29

MOT test number

971871756188

Result**✓ Passed****Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))**Advice** Nearside Rear Nail in tyre**MOT #17**

2019-02-06 14:28

MOT test number

343017001166

Result**✓ Passed****Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))**Advice** Brake pipe corroded, covered in grease or other material front and rear (1.1.11 (c))**Advice** Corrosion in several areas not excessive at time of test

**MOT #16** 2019-02-01 16:28**MOT test number** 149199141513**Result** ✗ Failed**Fail** Nearside Outer Seat belt anchorage prescribed area strength or continuity significantly reduced sill (7.1.1 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Corrosion in several areas not excessive at time of test**Advice** Brake pipe corroded, covered in grease or other material front and rear (1.1.11 (c))**Minor** Headlamp lens slightly defective both (4.1.1 (b) (i))**MOT #15** 2018-02-24 11:48**MOT test number** 266408214245**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit offside and nearside (4.1.E.1)**Advice** Rear Brake pipe slightly corroded offside and nearside (3.6.B.2c)**MOT #14** 2017-02-13 09:04**MOT test number** 509875881920**Result** ✓ Passed**MOT #13** 2016-02-15 12:12**MOT test number** 638829342614**Result** ✓ Passed**MOT #12** 2015-02-28 09:57**MOT test number** 186339855015**Result** ✓ Passed

**MOT #11** 2015-02-28 09:57**MOT test number** 736429855045**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #10** 2014-07-15 12:36**MOT test number** 848416194137**Result** ✓ Passed**MOT #9** 2014-07-14 14:08**MOT test number** 909945694199**Result** ✗ Failed**Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (1.7.5a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #8** 2013-07-12 10:36**MOT test number** 649913393184**Result** ✓ Passed**MOT #7** 2012-06-15 14:47**MOT test number** 628167662110**Result** ✓ Passed



MOT #6	2011-06-17 15:50
---------------	------------------

MOT test number	829038461173
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2010-06-11 13:13
---------------	------------------

MOT test number	964602060191
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2009-06-24 15:35
---------------	------------------

MOT test number	980075779125
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2008-03-10 10:22
---------------	------------------

MOT test number	511240678077
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2007-03-12 11:20
---------------	------------------

MOT test number	674411977097
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2006-01-13 10:39
---------------	------------------

MOT test number	492263616016
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
29 July 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	LM02OKP
Plate since	2024-03-29
Current registration	LM02OKP
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2002-06-25
Last registration	2023-07-10
Complete history	See info



Registration #1	2002-06-25	28 mi
Registration #2	2006-01-13	22.227 mi
Registration #3	2007-03-12	38.528 mi
Registration #4	2008-03-10	48.223 mi
Registration #5	2009-06-24	60.594 mi
Registration #6	2010-06-11	69.232 mi
Registration #7	2011-06-17	77.560 mi
Registration #8	2012-06-15	86.724 mi
Registration #9	2013-07-12	95.454 mi
Registration #10	2014-07-14	51.378 mi
Registration #11	2014-07-15	51.378 mi
Registration #12	2015-02-28	124.520 mi
Registration #13	2016-02-15	128.893 mi
Registration #14	2016-02-15	128.893 mi
Registration #15	2016-02-15	128.893 mi
Registration #16	2016-02-15	128.893 mi
Registration #17	2016-02-15	128.893 mi
Registration #18	2016-02-15	128.893 mi
Registration #19	2016-02-15	128.893 mi
Registration #20	2016-02-15	128.893 mi
Registration #21	2016-02-15	128.893 mi
Registration #22	2016-02-15	128.893 mi
Registration #23	2016-02-15	128.893 mi
Registration #24	2016-02-15	128.893 mi
Registration #25	2016-02-15	128.893 mi



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1700 mm
Length	3865 mm
Wheel base	2280 mm
Kerb weight	1235 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1ZZ1022556