



report date: 2024-03-29

## General information

Make	VOLVO
Model	XC90 D5 ACTIVE AWD
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	182 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.4 mpg
Consumption extra urban	40.4 mpg
Consumption combined	33.2 mpg
CO2 emission	224 g/km
CO2 label	K





## MOT history

MOT expiry date	2023-04-21
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	21
Total items failed	13

MOT #13 2022-04-22 09:46

MOT test number 170739410204

Result ✓ Passed

Next expiry date 2023-04-21

**Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Front Lower Axle swivel pins and bushes swivel pin and/or bush slightly worn x2 (5.1.2 (b) (i))

**Advice** Rear Tyre worn close to legal limit/worn on edge x2 (5.2.3 (e))

MOT #12 2021-04-07 13:58

MOT test number 360569868641

Result ✓ Passed

**Advice** Parking brake efficiency just met needs some adjustments/repairs

MOT #11 2021-04-07 13:58

MOT test number 239504594975

Result ✗ Failed

**Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Advice** Parking brake efficiency just met needs some adjustments/repairs

**Pass with rectification** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))



<b>MOT #10</b>	2019-06-11 10:09
<b>MOT test number</b>	547735187517
<b>Result</b>	✓ Passed
<b>Advice</b>	Near side and off side steering arms are worn

<b>MOT #9</b>	2019-06-06 15:41
<b>MOT test number</b>	559086096491
<b>Result</b>	✗ Failed
<b>Fail</b>	Parking brake inoperative on one side (1.4.1 (a))
<b>Advice</b>	Near side and off side steering arms are worn
<b>Fail</b>	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
<b>Fail</b>	Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
<b>Fail</b>	Nearside Front Position lamp not working (4.2.1 (a))

<b>MOT #8</b>	2018-04-11 08:25
<b>MOT test number</b>	131504549310
<b>Result</b>	✓ Passed
<b>Advice</b>	Screen is chipped
<b>Advice</b>	Engine is leaking oil

<b>MOT #7</b>	2018-04-11 07:34
<b>MOT test number</b>	204561786801
<b>Result</b>	✗ Failed
<b>Fail</b>	Electronic stability system warning lamp indicates a fault (3.4.1c)
<b>Advice</b>	Engine is leaking oil
<b>Fail</b>	Nearside Front position lamp(s) not working (1.1.A.3b)
<b>Advice</b>	Screen is chipped



<b>MOT #6</b>	2017-04-12 12:01
<b>MOT test number</b>	476197716710
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside rear twin side not working
<b>Advice</b>	Centre seat belt buckles stiff in operation

<b>MOT #5</b>	2017-04-12 12:01
<b>MOT test number</b>	870151673039
<b>Result</b>	✗ Failed
<b>Advice</b>	Nearside rear twin side not working
<b>Pass with rectification</b>	Electronic stability system warning lamp indicates a fault (3.4.1c)
<b>Advice</b>	Centre seat belt buckles stiff in operation

<b>MOT #4</b>	2016-04-13 12:25
<b>MOT test number</b>	385761995942
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear indicators are faded and close to a failure

<b>MOT #3</b>	2016-04-06 11:30
<b>MOT test number</b>	994836242887
<b>Result</b>	✗ Failed
<b>Fail</b>	Nearside Rear position lamp(s) not working (1.1.A.3b)
<b>Advice</b>	Rear indicators are faded and close to a failure
<b>Fail</b>	Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)
<b>Fail</b>	Offside Front position lamp(s) not working (1.1.A.3b)
<b>Advice</b>	Rear brake discs are worn
<b>Fail</b>	Offside Rear Brake pad(s) less than 1.5 mm thick outer (3.5.1g)



MOT #2	2015-03-19 10:13
MOT test number	368548575032
Result	✓ Passed
<div>Notice</div> Near side rear indicator is faded, traction control light was on temporarily but has now gone off	

MOT #1	2013-04-22 15:06
MOT test number	777882513136
Result	✓ Passed
<div>Notice</div> Offside front tyre outer sidewall is split	



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	<b>RO10DCZ</b>
Plate since	2024-03-29
Current registration	<b>RO10DCZ</b>
Plate since	2024-03-29

More info >





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-04-17
Last registration	2022-04-22
Complete history	<a href="#">See info</a>



Registration #1	2010-04-17	21 mi
Registration #2	2013-04-22	30.359 mi
Registration #3	2015-03-19	54.933 mi
Registration #4	2016-04-06	73.632 mi
Registration #5	2016-04-13	73.941 mi
Registration #6	2017-04-12	93.898 mi
Registration #7	2017-04-12	93.898 mi
Registration #8	2019-05-20	101.277 mi
Registration #9	2019-05-20	101.277 mi
Registration #10	2019-05-20	101.277 mi
Registration #11	2019-05-20	101.277 mi
Registration #12	2019-05-20	101.277 mi
Registration #13	2019-05-20	101.277 mi
Registration #14	2019-05-20	101.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4798 mm
Wheel base	2857 mm
Kerb weight	2130 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

**Engine number**

784551