





report date: 2024-03-28

General information

Make	PEUGEOT
Model	508 HDI SW ACTIVE NAVIGATION VERSION
Colour	Silver
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	240 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	52.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-07-05

Pictures 13

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



CA62ODC report date: 2024-03-28

MOT history

MOT expiry date	2024-07-05
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	4
Total items failed	6

MOT #12	2023-06-30 09:12	
MOT test number	982810378756	
Result	✓ Passed	
Next expiry date	2024-07-05	
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #3	11	2023-06-30 08:19
MOT te	st number	377184995595
Result		X Failed
Fail	Offside Front Seat belt retracting mechanism defective (7.1.2 (e))	
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Fail	Nearside Prop shaft joint constant velocity boot no longer prevents the ingress of	dirt (6.1.7 (g) (ii))
Fail	Nearside Headlamp aim unable to be tested (4.1.2 (b))	

MOT #10	2022-06-29 09:00
MOT test number	633549744805
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #9 2021-07-06 18:55

MOT test number 343073695752

MOT #8 2021-07-06 18:55

MOT test number 357659629152

Result X Failed

Pass with rectification Nearside Front Direction indicator not working (4.4.1 (a) (ii))

MOT #7 2021-01-29 17:19

MOT test number 272826791844

Result
✓ Passed

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #6 2021-01-29 09:09

MOT test number 926008227952

Result X Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #5 2020-01-18 09:36

MOT test number 500865681526

MOT #4 2019-01-26 09:26

MOT test number 440146650653

CarCheck.co.uk page 4/12



CA62ODC report date: 2024-03-28

MOT #3	2018-01-20 09:33
MOT test number	384981723070
Result	✓ Passed
MOT #2	2017-01-14 11:37
MOT test number	186052115401
Result	✓ Passed
MOT #1	2016-01-15 10:58
MOT test number	502432200583
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is		IGEOT

	More info	>
Plate changes		
See in this check if this PEUGEOT had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-31
Last registration	2023-06-30
Complete history	See info



Registration #1	2013-01-31	23 mi
Registration #2	2016-01-15	28.528 mi
Registration #3	2017-01-14	34.496 mi
Registration #4	2018-01-20	41.266 mi
Registration #5	2019-01-26	47.635 mi
Registration #6	2020-01-18	54.970 mi
Registration #7	2021-01-29	58.740 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es

7075.75.75

More info >

77,777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	90%
Children	87%
Pedestrian	41%
Safety systems	97%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1853 mm
Height	1476 mm
Length	4813 mm
Wheel base	2817 mm
Kerb weight	1578 kg
Max. allowed weight	2080 kg

Additional information

		•
Fuel tank capacity	72 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number JBEU3040389