





report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY TCE S/S
Colour	Blue
Year of manufacture	2013
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	190 Nm at 2.000 rpm
Engine capacity	1.199 сс
Cylinders	4
Fuel type	Petrol
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-23


Pictures 31

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-11
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	15
Total items failed	3

MOT #11	2023-10-04 09:57
MOT test number	164609114367
Result	✓ Passed
Next expiry date	2024-10-11
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #10		2023-10-04 09:13
MOT test	number	475815085771
Result		🗙 Failed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
MAJOR the ingress	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no s of dirt $(6.1.7 (g) (ii))$	longer prevents

MOT #9		2022-10-10 09:21
MOT test	number	831913639193
Result		✓ Passed
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice	Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/12



MOT #8 2022-10-07 09:15

MOT test number 472297889811

Result X Failed

MAJOR Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

DANGEROUS Exhaust shield missing where fitted as original equipment creating a risk of fire insecure (6.1.3 (e))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

MAJOR Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #7 2021-10-04 09:30

MOT test number 931435419588

Result
✓ Passed

Advice Front Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii))

MOT #6 2020-09-28 13:36

MOT test number 215580222340

Result

Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #5 2019-09-24 11:47

MOT test number 702330735040

CarCheck.co.uk page 4/12



MOT #4 2018-10-02 09:49 **MOT test number** 624383207212 Result ✓ Passed MOT #3 2017-09-20 11:03 **MOT** test number 907646126168 ✓ Passed Result MOT #2 2017-09-18 15:15 **MOT test number** 613447049974 Result × Failed Fail Nearside Rear rear brake binding (3.7.B.1) Fail Parking brake lever pawl spring does not push the pawl positively into the ratchet teeth (3.1.5) Fail Offside Front Seat belt stitching badly frayed (5.2.2b)

MOT #1	2016-09-30 13:41
MOT test number	718935667176
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	11 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.	THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR	
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.	*************	
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.	STREET, STREET	
Plate changes See in this check if this RENAULT had different number plates.		
Plate changes See in this check if this RENAULT had different number plates.	**************	
Plate changes See in this check if this RENAULT had different number plates.		
See in this check if this RENAULT had different number plates.		More info >
See in this check if this RENAULT had different number plates.		
業 以 以 以 以 以 以 以 以 以 以 以 以 以	Plate changes	
業 以 以 以 以 以 以 以 以 以 以 以 以 以	Continue to the selection of the selecti	
UK UK	See in this check if this RENAULT had different number plates.	
UK UK		
UK UK	Number of plates	,
UK UK		
Platte since	Current registration	NK NE
Platte since	Plate since	
Platte since		
More info	Current registration	UK UK
More info	Plate since	
More info		
Hore into		More info >

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-10-12
Last registration	2023-10-04
Complete history	See info



Registration #1	2013-10-12	8 mi
Registration #2	2016-09-30	23.250 mi
Registration #3	2017-09-18	30.594 mi
Registration #4	2017-09-20	30.594 mi
Registration #5	2018-10-02	31.459 mi
Registration #6	2019-09-24	32.664 mi
Registration #7	2020-09-28	33.561 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.177 ms
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1808 mm
Height	1471 mm
Length	4295 mm
Wheel base	2641 mm
Kerb weight	1205 kg
Max. allowed weight	1787 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/

Number of axles 2

Engine number D022899