



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Silver
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	41.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	48.7 mpg
CO2 emission	154 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-08
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-06
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	22
Total items failed	13

MOT #15	2023-06-28 12:40
MOT test number	897543077633
Result	✓ Passed
Next expiry date	2024-07-06
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2023-06-28 07:58
MOT test number	278935341626
Result	✗ Failed
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
Advice	Child Seat fitted not allowing full inspection of adult belt
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Fail	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #13**

2022-07-06 11:31

MOT test number

765575159260

Result

✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nail in n/s/r tyre**MOT #12**

2022-06-30 09:47

MOT test number

625145671429

Result

✗ Failed

Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Nearside Body component damaged and likely to cause injury mirror housing (6.2.1 (a) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nail in n/s/r tyre**Fail** Offside Side repeater not working (4.4.1 (a) (ii))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #11**

2021-06-29 11:48

MOT test number

104379465971

Result

✓ Passed

MOT #10

2021-06-28 14:40

MOT test number

401293867820

Result

✗ Failed

Fail Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #9** 2020-07-07 14:05**MOT test number** 280721143754**Result** ✓ Passed**Advice** Both front tyres worn on edges and winter tread pattern**Advice** Rear brake pads worn low**Advice** Rear brake discs heavily worn**MOT #8** 2020-07-06 11:19**MOT test number** 644543546445**Result** ✗ Failed**Advice** Rear brake discs heavily worn**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm 225/55x18 (5.2.3 (e))**Fail** Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Both front tyres worn on edges and winter tread pattern**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Rear brake pads worn low**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #7** 2019-04-29 10:01**MOT test number** 268494472198**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #6** 2018-05-14 11:52**MOT test number** 539003712282**Result** ✓ Passed**MOT #5** 2018-05-14 11:52**MOT test number** 755475340631**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2017-05-02 10:50**MOT test number** 655983935511**Result** ✓ Passed**MOT #3** 2016-04-20 09:13**MOT test number** 505135922941**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2015-04-20 08:59**MOT test number** 755890515144**Result** ✓ Passed**MOT #1** 2014-05-16 11:48**MOT test number** 197606734140**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
6 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	6 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-05-06
Last registration	2023-06-28
Complete history	See info



Registration #1	2011-05-06	25 mi
Registration #2	2014-05-16	35.032 mi
Registration #3	2015-04-20	40.031 mi
Registration #4	2016-04-20	52.036 mi
Registration #5	2017-05-02	58.615 mi
Registration #6	2018-05-14	65.850 mi
Registration #7	2018-05-14	65.850 mi
Registration #8	2019-04-29	73.458 mi
Registration #9	2020-07-06	84.967 mi
Registration #10	2020-07-06	84.967 mi
Registration #11	2020-07-06	84.967 mi
Registration #12	2020-07-06	84.967 mi
Registration #13	2020-07-06	84.967 mi
Registration #14	2020-07-06	84.967 mi
Registration #15	2020-07-06	84.967 mi
Registration #16	2020-07-06	84.967 mi
Registration #17	2020-07-06	84.967 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1679 kg
Max. allowed weight	2140 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4HAAU335555