



CITROËN



report date: 2024-03-29

## General information

Make	CITROEN
Model	XSARA 16V SX
Colour	Silver
Year of manufacture	2007
Top speed	118 mph
0 - 60 mph	11.5 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	110 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	172 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-01-30
Pictures	30
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2023-04-09
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	24
Total items failed	10

MOT #16	2022-04-10 09:42
MOT test number	849138300200
Result	✓ Passed
Next expiry date	2023-04-09

MOT #15	2022-04-06 13:40
MOT test number	428519575512

Result	✗ Failed
--------	----------

- Fail** Nearside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill holed (6.1.1 (c) (i))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Fail** Offside Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill x 2 holes (6.1.1 (c) (i))

**MOT #14**

2021-01-22 15:07

**MOT test number**

831589607968

**Result**

✓ Passed

- Advice** Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Advice** Exhaust corroded
- Advice** Power steering ram has slight seepage from a joint damper (2.1.5 (a))
- Advice** Front Tyre worn close to legal limit/worn on edge both bald (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Brake hose has slight corrosion to ferrule all hard to see (1.1.12 (f) (i))

**MOT #13**

2021-01-08 15:32

**MOT test number**

545073482020

**Result**

✗ Failed

- Advice** Front Tyre worn close to legal limit/worn on edge both bald (5.2.3 (e))
- Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Rear Brake hose has slight corrosion to ferrule all hard to see (1.1.12 (f) (i))
- Advice** Exhaust corroded
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Suspension component pin or bush slightly worn (5.3.4 (a) (i))
- Advice** Power steering ram has slight seepage from a joint damper (2.1.5 (a))

**MOT #12**

2019-07-30 12:30

**MOT test number**

161850854705

**Result**

✓ Passed

**Advice** Nearside Suspension component pin or bush slightly worn wishbone (5.3.4 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Steering damper leaking**MOT #11**

2019-07-24 15:06

**MOT test number**

504693272138

**Result**

✗ Failed

**Advice** Steering damper leaking**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Nearside Suspension component pin or bush slightly worn wishbone (5.3.4 (a) (i))**MOT #10**

2018-07-26 16:05

**MOT test number**

613117523333

**Result**

✓ Passed

**MOT #9**

2017-07-28 12:06

**MOT test number**

255502860423

**Result**

✓ Passed

**Advice** Rear Passenger seat(s) missing at time of test seats 4,6 and 7 missing

**MOT #8** 2017-07-25 15:26**MOT test number** 167681261705**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Nearside Front Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)**Advice** Rear Passenger seat(s) missing at time of test seats 4,6 and 7 missing**Fail** Rear Exhaust has a major leak of exhaust gases silencer corroded (7.1.2)**Fail** Offside Front Seat belt anchorage prescribed area is excessively corroded outer sill (5.2.6)**MOT #7** 2016-07-28 09:28**MOT test number** 417753893908**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases rear (7.1.2)**MOT #6** 2015-07-30 12:03**MOT test number** 246291015222**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #5** 2014-11-20 10:02**MOT test number** 405494824367**Result** ✓ Passed**MOT #4** 2013-11-19 09:24**MOT test number** 315373823397**Result** ✓ Passed



MOT #3	2012-11-08 09:31
MOT test number	776833012355
Result	✓ Passed
MOT #2	2011-10-27 14:07
MOT test number	968650801320
Result	✓ Passed
MOT #1	2010-10-26 09:16
MOT test number	753519190228
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-11-22
Last registration	2022-04-10
Complete history	<a href="#">See info</a>



Registration #1	2007-11-22	11 mi
Registration #2	2010-10-26	26.182 mi
Registration #3	2011-10-27	33.087 mi
Registration #4	2012-11-08	41.224 mi
Registration #5	2013-11-19	50.127 mi
Registration #6	2014-11-20	60.136 mi
Registration #7	2015-07-30	65.672 mi
Registration #8	2016-07-28	73.199 mi
Registration #9	2017-07-25	78.638 mi
Registration #10	2018-05-22	85.277 mi
Registration #11	2019-05-22	95.277 mi
Registration #12	2020-05-22	105.277 mi
Registration #13	2021-05-22	115.277 mi
Registration #14	2022-05-22	125.277 mi
Registration #15	2023-05-22	135.277 mi
Registration #16	2024-05-22	145.277 mi
Registration #17	2025-05-22	155.277 mi
Registration #18	2026-05-22	165.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1667 mm
Height	1521 mm
Length	3850 mm
Wheel base	2460 mm
Max. allowed weight	1597 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FX6F3239543