





report date: 2024-03-29

General information

| Make | TOYOTA |
|---------------------|-----------------|
| Model | VERSO D-4D ICON |
| Colour | Blue |
| Year of manufacture | 2015 |
| Top speed | 112 mph |
| 0 - 60 mph | 12.7 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 112 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 2.400 rpm |
| Engine capacity | 1.598 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 68.9 mpg |
| Consumption combined | 62.8 mpg |
| CO2 emission | 119 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



Internet history

Entry 3

Date 2021-11-04

Pictures 27

Listing price <u>View report</u>









source: yesauto.com

Entry 2

| Date | 2021-10-26 |
|------|------------|
| | |

Pictures 29

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

| Date | 2021-10-25 |
|----------|------------|
| Pictures | 1 |

Listing price <u>View report</u>



source: autotrader.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2024-08-23 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 6 |

| MOT #5 | 2023-08-02 14:29 |
|------------------|------------------|
| MOT test number | 657345842352 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-23 |

| MOT #4 | 2023-08-02 08:23 |
|--|-----------------------|
| MOT test number | 241954633984 |
| Result | × Failed |
| Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) | |
| Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Advice Offside Front Tyre worn close to legal limit/worn on edge edge (5.2.3 (e)) | |
| Fail Offside Rear Tyre has a lump, caused by separation or partial failure of its struct | ture (5.2.3 (d) (ii)) |
| Fail Offside Front Headlamp light intensity severely reduced (4.1.4 (a)) | |
| Fail Nearside Front Tyre has ply or cords exposed sidewall (5.2.3 (d) (ii)) | |

CarCheck.co.uk page 3/11



MOT #1

RJ15SXN report date: 2024-03-29

2018-08-22 12:33

MOT #3 2022-08-19 10:52 **MOT test number** 544112461567 Result ✓ Passed **Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt Nearside Front Tyre slightly damaged Sidewall (5.2.3 (d) (ii)) **Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt **Advice** Advice Rear Passenger seat(s) missing at time of test 3rd row inaccessible Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii)) **Advice**

| MOT #2 | 2021-08-24 15:34 |
|-----------------|------------------|
| MOT test number | 407659316937 |
| Result | ✓ Passed |

| MOT test number | 604510412467 |
|-----------------|--------------|
| Result | ✓ Passed |

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 23 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r | |
|--|-------------|
| | |
| MARKET CONTRACTOR CONT | |
| | |
| | |
| ******** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this TOYOTA had different number plates. | |
| Number of plates | , |
| Current registration | UK PIE |
| Flate since | |
| Current registration | UK UK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2015-08-19 |
| Last registration | 2023-08-02 |
| Complete history | See info |



| Registration #1 | 2015-08-19 | 13 mi |
|-----------------|------------|-----------|
| Registration #2 | 2018-08-22 | 35.783 mi |
| Registration #3 | 2021-08-24 | 75.303 mi |
| Registration #4 | | 71.777 66 |
| Registration #5 | | 11.777 es |
| Registration #6 | | 71.777 66 |
| Registration #7 | | D.777 66 |
| Registration #8 | | 71.777 es |
| Registration #9 | | 11.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 89% |
| Children | 75% |
| Pedestrian | 69% |
| Safety systems | 86% |
| Overall rating | 82% |
| Video | see crash video |



Dimensions & weight

| Width | 1790 mm |
|---------------------|---------|
| Height | 1630 mm |
| Length | 4460 mm |
| Wheel base | 2780 mm |
| Kerb weight | 1620 kg |
| Max. allowed weight | 2260 kg |

Additional information

| Fuel tank capacity | 55 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 11/1 |

Number of axles 2

Engine number N470649294