





report date: 2024-03-28

## General information

Make	MAZDA
Model	6 TS
Colour	Silver
Year of manufacture	-
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	118 BHP
Max. torque	165 Nm at 4.300 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.2 mpg



CarCheck.co.uk page 1/13



report date: 2024-03-28

## **MOT** history

MOT #18 2022-01-29 11:52

MOT test number 703784007411

**Result** ✓ Passed

Next expiry date 2023-02-14

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))

**Advice** All rear suspension components corroded

**MOT #17** 2021-02-15 17:44

**MOT test number** 129423174843

**Result** 
✓ Passed

CarCheck.co.uk page 2/13



**Advice** 

Suspension parts corroded

TN07XUV

report date: 2024-03-28

**MOT #16** 2021-01-21 13:56

MOT test number 413449143630

Result **X** Failed **Advice** Rear Coil spring corroded both (5.3.1 (b) (i)) Fail Offside Front Suspension arm ball joint likely to become detached lower rear (5.3.4 (a) (ii)) Offside Front Service brake excessively binding (1.2.1 (f)) Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail **Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Fail Front Brakes imbalanced across an axle Axle 1 (1.2.1 (b) (i)) Both sills corroded **Advice Advice** Exhaust flange corroded Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) Fail Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Front Service brake imbalanced across an axle (1.2.1 (b) (i)) Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i)) Advice **Advice** Bonnet safety latch siezed Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i)) Fail

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT test number

Result

Advice Underside suspension corroded

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust corroded at rear join

MOT #14 2020-01-09 10:33 **MOT** test number 814029068309 Result × Failed **Advice** Underside suspension corroded Fail Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) Fail Nearside Front Tyre not fitted in accordance with side wall instructions wrong rotation (5.2.3 (i)) **Advice** Exhaust corroded at rear join Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2019-01-21 12:56

MOT test number 739381841213

Result ✓ Passed

 MOT #12
 2017-07-26 13:21

 MOT test number
 103008546827

 Result
 ✓ Passed

CarCheck.co.uk page 4/13



report date: 2024-03-28

**MOT #11** 2017-07-26 08:59

**MOT test number** 894894904555

**Result** X Failed

**Fail** Offside Front Brake pipe excessively corroded exposed part to flex hose (3.6.B.2c)

**Fail** Nearside Front coil spring broken (2.4.C.1a)

**MOT #10** 2016-07-26 15:14

**MOT test number** 560141965993

**Result** ✓ Passed

MOT #9 2016-07-25 15:21

**MOT test number** 962757633390

Result X Failed

**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

Fail Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**Fail** Nearside Stop lamp not working (1.2.1b)

**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

**Fail** Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)

**Fail** Front position lamp(s) not working (1.1.A.3b)

**Fail** Registration plate lamp not working (1.1.C.1d)

MOT #8 2015-07-15 13:37

MOT test number 257836895458

**Result** 
✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #7 2014-08-01 13:10

**MOT test number** 986723214206

**Result** ✓ Passed

MOT #6 2014-08-01 10:36

**MOT test number** 768003014209

Result X Failed

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Offside Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

MOT #5 2013-06-28 14:51

**MOT test number** 589619373146

**Result** ✓ Passed

**MOT #4** 2012-06-21 15:28

**MOT test number** 736573772102

Result 

Passed

MOT #3 2012-06-21 11:25

**MOT test number** 758853972138

Result × Failed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2011-06-27 10:14

**MOT test number** 747898471164

**Result** ✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

MOT #1 2010-07-23 10:03

**MOT test number** 153504700265

CarCheck.co.uk page 7/13



report date: 2024-03-28

### Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



TNO7XUV report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history	Owner	history
---------------	-------	---------

For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full		4
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		1.01.0
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



TNO7XUV report date: 2024-03-28

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-07-31
Last registration	2022-01-29
Complete history	See info



Registration #1	2007-07-31	12 mi
Registration #2	2010-07-23	10.892 mi
Registration #3	2011-06-27	17.217 mi
Registration #4	2012-06-21	24.121 mi
Registration #5	2012-06-21	24.121 mi
Registration #6	2013-06-28	32.390 mi
Registration #7	2014-08-01	40.729 mi
Registration #8	2014-08-01	40.729 mi
Registration #9	2015-07-15	58.807 mi
Registration #10	2016-07-25	70.543 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.177 ms

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1780 mm
Height	1435 mm
Length	4690 mm
Wheel base	2675 mm
Kerb weight	1384 kg
Max. allowed weight	1870 kg

# Additional information

Fuel tank capacity	64 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	L8 20220746

CarCheck.co.uk page 13/13