





report date: 2024-03-29

General information

Make	PEUGEOT
Model	206 ALLURE COUPE CABRIOLET
Colour	Red
Year of manufacture	2006
Top speed	120 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	166 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



WD55RVY
report date: 2024-03-29

MOT history

MOT expiry date	2021-11-29
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	17
Total items failed	6

MOT #14		2020-11-20 10:50
MOT test	number	162613817270
Result		✓ Passed
Next expi	y date	2021-11-29
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened	ed (1.1.14 (a) (ii))
Advice	Both front top mount bearings creaking on lock to lock check	
Advice	Nearside Front Road wheel slightly distorted slight damage to outer rim ((5.2.2 (c) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both	sides (1.1.14 (a) (ii))

MOT #13	2019-05-30 15:47
MOT test number	855590873714
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT #12 2019-05-29 11:20

MOT test number 839333338928

Result X Failed

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a))

MOT #11 2018-04-30 15:48

MOT test number 805082681914

Result \rightarrow Passed

MOT #10 2017-05-10 11:19

MOT test number 303974719120

Result ✓ Passed

MOT #9 2016-05-26 08:58

MOT test number 304452846613

Result / Passed

Advice Nearside Rear Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

Advice Fuel tank straps corroding

MOT #8 2015-05-28 16:49

MOT test number 479608145109

Result ✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Rear fog lamp not working (1.3.2b)

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

 MOT #6
 2014-05-12 13:01

 MOT test number
 206582534180

 Result
 ✓ Passed

MOT #5 2013-05-10 18:08 **MOT** test number 898100733193 Result ✓ Passed **Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) **Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) **Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7) **Notice** Exhaust system has various areas of corrosion

MOT #4

MOT test number

276515672177

Result

Notice Front brake discs worn thin and corroded on the inside face

Notice Rear silencer corroded

CarCheck.co.uk page 4/11



report date: 2024-03-29

MOT #3 2011-06-28 15:43 **MOT test number** 406599071146 ✓ Passed Result MOT #2 2010-01-11 08:51 **MOT test number** 380771710040 ✓ Passed Result MOT #1 2009-01-09 12:04 541749909026 **MOT test number** Result ✓ Passed

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	hictory
Owner	HISLOIV

For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-01-18
Last registration	2020-11-20
Complete history	See info



Registration #1	2006-01-18	20 mi
Registration #2	2009-01-09	20.635 mi
Registration #3	2010-01-11	27.429 mi
Registration #4	2011-06-28	36.787 mi
Registration #5	2012-06-23	43.128 mi
Registration #6	2013-05-10	44.612 mi
Registration #7	2014-05-12	50.592 mi
Registration #8	2015-05-28	58.318 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.177 ms

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1673 mm
Height	1373 mm
Length	3835 mm
Wheel base	2442 mm
Kerb weight	1215 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	47 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	4 page 11/11

Number of axles 2

Engine number FX6N2895274