





General information

Make	HONDA
Model	FR-V VTEC SPORT
Colour	Blue
Year of manufacture	2006
Top speed	120 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.6 mpg
CO2 emission	199 g/km
CO2 label	J







Internet history

Entry	1

Date Pictures 2021-08-05

14

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-24
MOT pass rate	79 %
MOT passed	15
Failed MOT tests	4
Total advice items	20
Total items failed	3

MOT #19	2023-07-25 13:28
MOT test number 790324692	
Result	✓ Passed
Next expiry date	2024-07-24
Advice Nearside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice Vehicle structure is corroded but structural rigidity is not significantly reduced underside of vehicle is rusty (6.1.1 (c) (i))	
Advice Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #18	2022-07-12 14:07
MOT test number	340119540304
Result	✓ Passed

MOT #17	2022-07-11 14:14
MOT test number	481867183701
Result	🗙 Failed

MAJOR Nearside Rear Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced (6.1.1 (c) (i))





MOT #16	2021-06-17 13:25
MOT test number	692723900417
Result	Passed
Advice Nearside Rear Lower Integral body structure is corroded but structural rigidity reduced has underseal protection (6.1.1 (c) (i))	is not significantly
Advice Underbody general minor corrosion has underseal coated suspension/chasis	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Rear Lower Integral body structure or chassis corroded within 30cm of seriously affecting overall security has underseal protection (6.2.2 (d) (i))	f a mounting, but not
Advice Coil spring corroded x4 (5.3.1 (b) (i))	

MOT #15	2020-10-03 11:13
MOT test number	878462847756
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #14		2020-09-30 15:29
MOT test	number	306761092723
Result		🗙 Failed
MAJOR	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice	Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #13	2019-10-07 08:51
MOT test number	788592113921
Result	✓ Passed
Advice Steering system slightly rough (2.1.1 (a))	
Advice Coil spring corroded all (5.3.1 (b) (i))	





MOT #12		2019-10-07 08:51
MOT test number		682065805129
Result		🗙 Failed
Pass with rectification	Offside Position lamp not working (4.2.1 (a) (ii))	
Advice Coil spring corro	ded all (5.3.1 (b) (i))	
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	
Advice Steering system	slightly rough (2.1.1 (a))	

MOT #11	2018-10-01 08:45
MOT test number	583307650616
Result	✓ Passed

MOT #10	2017-09-21 15:33
MOT test number	370693460499
Result	✓ Passed

МОТ #9	2016-09-29 13:17
MOT test number	369134030140
Result	✓ Passed

MOT #8		2016-09-29 13:17
MOT test number		872492276373
Result		🗙 Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	

MOT #7	2015-10-05 13:04
MOT test number	357645194130
Result	✓ Passed





MOT #6	2014-10-06 09:41
MOT test number	285419074257
Result	✓ Passed
MOT #5	2013-10-03 11:04
MOT test number	849196573271
Result	✓ Passed
MOT #4	2012-10-04 09:27
MOT test number	327838272444
Result	✓ Passed
MOT #3	2011-10-11 09:18
MOT test number	215584181227
Result	✓ Passed
MOT #2	2010-10-05 15:33
MOT test number	510008370286
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
MAT #1	

MOT #1	2009-10-09 09:16
MOT test number	571162189240
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 August 2024	✓ MOT Expires: 24 July 2024
Tax status	Valid until 1 August
Days left	94
MOT expiry date	24 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >





Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-10-10
Last registration	2023-07-25
Complete history	See info



Registration #1	2006-10-10	19 mi
Registration #2	2009-10-09	26.073 mi
Registration #3	2010-10-05	36.326 mi
Registration #4	2011-10-11	46.519 mi
Registration #5	2012-10-04	50.762 mi
Registration #6	2013-10-03	57.668 mi
Registration #7	2014-10-06	62.260 mi
Registration #8	2015-10-05	66.284 mi
Registration #9	2016-09-29	70.722 mi
Registration #10	2016-09-29	70.722 mi
Registration #11	2017-09-21	75.784 mi
Registration #12		11.777 esi
Registration #13		11.777 esi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 est
Registration #17		11.777 esi
Registration #18		11.777 est
Registration #19		11.777 esi
Registration #20		11.777 est
Registration #21		11.777 esi

More info >





Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1447 kg
Additional information	
Fuel tank capacity	58 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	K20A92003809