



report date: 2024-03-28

General information

Make	FORD
Model	FUSION FUSION 2
Colour	Grey
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	124 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-29
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history****MOT #19** 2021-07-28 10:26**MOT test number** 772078863222**Result** ✓ Passed**Next expiry date** 2022-08-01**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #18** 2021-07-28 10:26**MOT test number** 591022750151**Result** ✗ Failed**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Front Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Pass with rectification** Inner Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Pass with rectification** Nearside Front Headlamp aim too high (4.1.2 (a))**MOT #17** 2020-07-31 11:59**MOT test number** 156050884975**Result** ✓ Passed

- Advice** Nearside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #16** 2019-08-02 13:01**MOT test number** 115424189117**Result** ✓ Passed

**Advice** Offside Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**Advice** Nearside Front Headlamp has a product on the light source but not seriously reducing light output (4.1.4 (b))

**MOT #15** 2018-07-23 13:19**MOT test number** 486656899748**Result** ✓ Passed

**Advice** Headlamp has a product on the lens but not seriously reducing light output both side (4.1.4 (b))

**MOT #14** 2017-07-17 12:15**MOT test number** 898276390499**Result** ✓ Passed

**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #13** 2016-07-26 15:48**MOT test number** 227289555249**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #12** 2016-07-26 15:48**MOT test number** 733262665732**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2015-07-18 10:47**MOT test number** 737139995186**Result** ✓ Passed**MOT #10** 2015-07-18 10:47**MOT test number** 956689695197**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #9** 2015-07-17 17:42**MOT test number** 217028895433**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Brake hose excessively deteriorated (3.6.B.4d)**Advice** Nearside Front Brake hose slightly deteriorated (3.6.B.4d)**Fail** Rear Stop lamp not working (1.2.1b)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**MOT #8** 2013-12-14 12:48**MOT test number** 647148843371**Result** ✓ Passed**MOT #7** 2012-08-17 12:41**MOT test number** 397050432423**Result** ✓ Passed**MOT #6** 2012-08-17 12:41**MOT test number** 315680932290**Result** ✗ Failed**Pass with rectification** Offside Front Direction indicator incorrect colour (1.4.A.2f)**MOT #5** 2011-08-16 18:06**MOT test number** 525598521273**Result** ✓ Passed



MOT #4	2010-08-04 10:36
MOT test number	764366410243
Result	✓ Passed

MOT #3	2010-08-03 12:23
MOT test number	751035710263
Result	✗ Failed
Fail	Hazard warning lamps not flashing in phase, with ignition on (1.4.B.1f)
Fail	Hazard warning switch faulty (1.4.B.1d)

MOT #2	2009-03-27 14:31
MOT test number	580486989029
Result	✓ Passed

MOT #1	2008-03-28 09:15
MOT test number	271548988077
Result	✓ Passed





Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-28
Current registration	*****
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2005-04-29
Last registration	2021-07-28
Complete history	<a href="#">See info</a>



Registration #1	2005-04-29	21 mi
Registration #2	2008-03-28	11.357 mi
Registration #3	2009-03-27	15.765 mi
Registration #4	2010-08-03	24.737 mi
Registration #5	2010-08-04	24.739 mi
Registration #6	2011-08-16	31.813 mi
Registration #7	2012-08-17	38.997 mi
Registration #8	2013-12-14	49.017 mi
Registration #9	2015-07-17	57.420 mi
Registration #10	2015-07-18	57.425 mi
Registration #11	2016-01-29	58.337 mi
Registration #12	2016-01-29	58.337 mi
Registration #13	2016-01-29	58.337 mi
Registration #14	2016-01-29	58.337 mi
Registration #15	2016-01-29	58.337 mi
Registration #16	2016-01-29	58.337 mi
Registration #17	2016-01-29	58.337 mi
Registration #18	2016-01-29	58.337 mi
Registration #19	2016-01-29	58.337 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1952 mm
Height	1534 mm
Length	4020 mm
Wheel base	2485 mm
Kerb weight	1082 kg
Max. allowed weight	1605 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number	5J13755
---------------	---------