





General information

Make	HYUNDAI
Model	140 CRDI STYLE BLUE DRIVE
Colour	White
Year of manufacture	2014
Top speed	118 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	С





Internet history

Entry 1

Date Pictures 2021-07-14

19

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-08
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	19
Total items failed	5

MOT #9	2023-10-09 11:52
MOT test number	969889065475
Result	✓ Passed
Next expiry date	2024-10-08
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Nearside Play in steering rack inner joint(s)	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #8	2023-10-03 16:08
MOT test number	723551017728
Result	× Failed
Advice Nearside Play in steering rack inner joint(s)	
Fail Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))	
FailNearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	



HN64NHJ
report date: 2024-03-29

MOT #7		2022-08-24 13:12
MOT test	number	461407326407
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

МОТ #6	2022-08-23 14:40
MOT test number	186278571250
Result	🗙 Failed
Advice Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #5		2021-08-24 10:45
MOT test	number	868953120466
Result		✓ Passed
Advice	Undertrays fitted	
Advice	Front Inner Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))	

MOT #4	2020-11-02 15:13
MOT test number	815582311130
Result	✓ Passed





MOT #3		2019-11-01 09:10
MOT test	number	557719742733
Result		✓ Passed
MOT #2		2018-11-13 09:25
MOT test	number	136829416350
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Items removed from driver's view prior to test dash cam power cable ob	ostructing view of road
MOT #1		2017-10-26 08:23
MOT test	number	263918272369
Result		🗸 Passed



Tax & MOT check

✓ Taxed Tax due: 1 February 2025	✓ MOT Expires: 8 October 2024
Tax status	Valid until 1 February
Days left	278
MOT expiry date	8 October 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report here.

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-11-21
Last registration	2023-10-09
Complete history	See info



Registration #1	2014-11-21	19 mi
Registration #2	2017-10-26	31.896 mi
Registration #3	2018-11-13	52.726 mi
Registration #4	2019-11-01	72.583 mi
Registration #5	2020-11-02	80.390 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi





Car features

50225	Air conditioning
50295	
50482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight	
Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1638 kg
Max. allowed weight	2120 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of ax	des
--------------	-----

Engine number

2

D4FDEU469745