



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD 16V
Colour	Red
Year of manufacture	2000
Top speed	150 mph
0 - 60 mph	6.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	236 BHP
Max. torque	204 Nm at 7.500 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	21.2 mpg
Consumption extra urban	35.8 mpg
Consumption combined	28.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-15
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-02-06
MOT pass rate	67 %
MOT passed	16
Failed MOT tests	8
Total advice items	45
Total items failed	5

MOT #24	2022-02-07 14:22
MOT test number	925800810825
Result	✓ Passed
Next expiry date	2023-02-06

MOT #23	2022-01-22 16:48
MOT test number	976718464554
Result	✗ Failed
<div><div>MAJOR</div>Offside Rear Inner Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))</div>	
<div><div>Advice</div>Under carriage surface rust sill covers fitted</div>	

**MOT #22**

2021-10-13 12:03

MOT test number

656067904986

Result**✗ Failed**

MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))

Advice Offside Front Play in steering rack inner joint(s)

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Minor Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))

MAJOR Offside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #21

2020-03-10 14:58

MOT test number

352720329676

Result**✓ Passed**

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2020-03-10 12:00

MOT test number

192285994201

Result**✗ Failed****Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Front Headlamp lens slightly defective both (4.1.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Other passenger door cannot be opened from outside the vehicle and inside (6.2.3 (a))**Advice** Rear Direction indicator slightly discoloured both (4.4.3 (a))**MOT #19**

2019-03-26 14:35

MOT test number

575462108956

Result**✓ Passed****Advice** Body panel slightly loose FRONT BUMPER (6.2.1 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))

**MOT #18**

2019-03-26 11:51

MOT test number

960189466489

Result**✗ Failed****Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**MAJOR** Offside Rear Position lamp not working (4.2.1 (a))**Advice** Body panel slightly loose FRONT BUMPER (6.2.1 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a))**MOT #17**

2018-03-27 14:36

MOT test number

478753189066

Result**✓ Passed****Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)**Advice** Front engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)**Advice** Offside Headlamp deteriorated but light output not reduced (1.7.5a)**MOT #16**

2017-03-23 17:14

MOT test number

843964234379

Result**✓ Passed**

**MOT #15** 2017-03-23 17:14**MOT test number** 374865518982**Result** ✗ Failed

Pass with rectification Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

Pass with rectification Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)

MOT #14 2017-03-16 14:53**MOT test number** 647399474720**Result** ✗ Failed

Fail Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

Advice Engine management light on

MOT #13 2016-03-24 14:56**MOT test number** 650223548546**Result** ✓ Passed

Advice Front engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

MOT #12 2016-03-23 13:18**MOT test number** 857693983897**Result** ✗ Failed

Fail Offside Steering rack gaiter split (2.2.D.2d)

Advice Engine management light on

Advice Front engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

MOT #11 2015-03-25 12:39**MOT test number** 469254285027**Result** ✓ Passed

Advice Front engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

**MOT #10** 2014-04-01 15:05**MOT test number** 167201394038**Result** ✓ Passed**MOT #9** 2014-04-01 15:05**MOT test number** 586411194063**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (1.8)**MOT #8** 2013-03-22 11:54**MOT test number** 385781683045**Result** ✓ Passed**MOT #7** 2012-03-07 10:36**MOT test number** 197757162096**Result** ✓ Passed**Notice** Nail in offside rear tyre**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #6** 2011-03-30 11:48**MOT test number** 626259081052**Result** ✓ Passed**MOT #5** 2010-04-01 12:10**MOT test number** 130311690026**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2009-04-03 12:43
MOT test number	702043199009
Result	✓ Passed
MOT #3	2008-03-27 13:49
MOT test number	823987871887
Result	✓ Passed
MOT #2	2007-03-23 16:47
MOT test number	682702787025
Result	✓ Passed
MOT #1	2006-03-23 14:47
MOT test number	113952086430
Result	✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2000-03-30
Last registration	2022-02-07
Complete history	See info



Registration #1	2000-03-30	22 mi
Registration #2	2006-03-23	43.557 mi
Registration #3	2007-03-23	49.220 mi
Registration #4	2008-03-27	53.485 mi
Registration #5	2009-04-03	58.123 mi
Registration #6	2010-04-01	62.764 mi
Registration #7	2011-03-30	67.128 mi
Registration #8	2012-03-07	71.151 mi
Registration #9	2013-03-22	75.322 mi
Registration #10	2014-04-01	79.164 mi
Registration #11	2015-03-25	82.488 mi
Registration #12	2016-03-23	85.402 mi
Registration #13	2016-03-24	85.402 mi
Registration #14	2016-03-24	85.402 mi
Registration #15	2016-03-24	85.402 mi
Registration #16	2016-03-24	85.402 mi
Registration #17	2016-03-24	85.402 mi
Registration #18	2016-03-24	85.402 mi
Registration #19	2016-03-24	85.402 mi
Registration #20	2016-03-24	85.402 mi
Registration #21	2016-03-24	85.402 mi
Registration #22	2016-03-24	85.402 mi
Registration #23	2016-03-24	85.402 mi
Registration #24	2016-03-24	85.402 mi
Registration #25	2016-03-24	85.402 mi



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1285 mm
Length	4135 mm
Kerb weight	1271 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	F20C21002819