




report date: 2024-03-28

General information

Make	CITROEN
Model	C2 16V VTS
Colour	Silver
Year of manufacture	2005
Top speed	126 mph
0 - 60 mph	8.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	142 Nm at 3.750 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-08-12
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-27
Pictures	20
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2022-09-28
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	37
Total items failed	13

MOT #192021-09-29 15:36

MOT test number302438415406

Result✓ Passed

Next expiry date2022-09-28

- AdviceFront number plate is cracked
- AdviceCorrosion to exhaust system
- AdviceNearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOffside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- AdviceBonnet prop missing
- AdviceCorrosion to chassis
- AdviceCorrosion to front brake discs

**MOT #18**

2020-12-08 17:23

MOT test number

152234614978

Result

✓ Passed

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))**MOT #17**

2020-12-07 14:39

MOT test number

551670860691

Result

✗ Failed

Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Horn not working (7.7 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Exhaust mounting defective (6.1.2 (a))

**MOT #16** 2019-12-02 14:14**MOT test number** 293239721132**Result** ✓ Passed**Advice** Various patches of corrosion on underside of vehicle**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Play in steering rack inner joint(s)**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #15** 2018-11-25 10:45**MOT test number** 399272813699**Result** ✓ Passed**MOT #14** 2017-12-11 11:04**MOT test number** 877683178634**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #13** 2016-10-10 15:37**MOT test number** 721633303684**Result** ✓ Passed**MOT #12** 2015-10-10 15:04**MOT test number** 256112225190**Result** ✓ Passed**Advice** N/S/F tyre worn on inner edge**Advice** O/S/F tyre worn on inner edge

**MOT #11** 2015-10-10 11:58**MOT test number** 860910397892**Result** ✗ Failed**Advice** N/S/F tyre worn on inner edge**Advice** O/S/F tyre worn on inner edge**Fail** Horn not working (1.6.2a)**MOT #10** 2014-06-16 12:57**MOT test number** 447577064138**Result** ✓ Passed**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**MOT #9** 2014-06-14 09:40**MOT test number** 366085064116**Result** ✗ Failed**Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)**MOT #8** 2013-06-20 08:51**MOT test number** 749481873184**Result** ✓ Passed

**MOT #7** 2013-06-19 14:06**MOT test number** 799880873199**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Rear registration plate character(s) incorrectly spaced (6.3.4a)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front registration plate character(s) incorrectly spaced (6.3.4a)**MOT #6** 2012-06-20 15:16**MOT test number** 349282772127**Result** ✓ Passed**MOT #5** 2012-06-19 17:06**MOT test number** 839721072100**Result** ✗ Failed**Advice** Nearside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**Advice** Offside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Front Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Notice** Front windscreen has an aftermarket sun strip fitted but is of a transparent type and not in the drivers view of the road or lower than the cleared view area by the washers/wipers.**Fail** Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Front Track rod end ball joint dust cover damaged, but preventing the ingress of dirt (2.2.C.1c)**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #4** 2011-06-06 12:47**MOT test number** 288377251445**Result** ✓ Passed



MOT #3	2010-01-27 16:37
MOT test number	243937020017
Result	✓ Passed

MOT #2	2010-01-27 10:05
MOT test number	804787820002
Result	✗ Failed
<div><div>Fail</div>Windscreen washer provides insufficient washer liquid (8.2.3)</div>	

MOT #1	2009-02-23 09:55
MOT test number	184144659402
Result	✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	BD55TVP
Plate since	2019-03-28
Current registration	BD55TVP
Plate since	2019-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-12-23
Last registration	2021-09-29
Complete history	See info



Registration #1	2005-12-23	21 mi
Registration #2	2009-02-23	15.463 mi
Registration #3	2010-01-27	18.616 mi
Registration #4	2010-01-27	18.616 mi
Registration #5	2011-06-06	31.515 mi
Registration #6	2012-06-19	38.870 mi
Registration #7	2012-06-20	38.870 mi
Registration #8	2013-06-19	46.617 mi
Registration #9	2013-06-20	46.617 mi
Registration #10	2014-06-14	47.394 mi
Registration #11	2014-06-16	47.395 mi
Registration #12	2015-06-14	55.277 mi
Registration #13	2015-06-16	55.277 mi
Registration #14	2015-06-18	55.277 mi
Registration #15	2015-06-20	55.277 mi
Registration #16	2015-06-22	55.277 mi
Registration #17	2015-06-24	55.277 mi
Registration #18	2015-06-26	55.277 mi
Registration #19	2015-06-28	55.277 mi
Registration #20	2015-06-30	55.277 mi
Registration #21	2015-07-02	55.277 mi
Registration #22	2015-07-04	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1659 mm
Height	1451 mm
Length	3666 mm
Wheel base	2315 mm
Kerb weight	1083 kg
Max. allowed weight	1394 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	FX4S2476190