



report date: 2024-03-28

General information

Make	MAZDA
Model	6 D S
Colour	Silver
Year of manufacture	-
Top speed	125 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	330 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)

**MOT history**

<b>MOT #19</b>	2023-01-31 12:18
<b>MOT test number</b>	577568083694
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-02-07
<b>Advice</b>	Amber DPF light flashing - no MIL light on though

<b>MOT #18</b>	2023-01-30 15:23
<b>MOT test number</b>	915265434320
<b>Result</b>	✗ Failed
<b>Fail</b>	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
<b>Fail</b>	Offside Front Headlamp aim too low (4.1.2 (a))
<b>Advice</b>	Amber DPF light flashing - no MIL light on though
<b>Fail</b>	Nearside Front Headlamp aim too low (4.1.2 (a))
<b>Fail</b>	Parking brake efficiency below requirements (1.4.2 (a) (i))

<b>MOT #17</b>	2022-02-08 13:56
<b>MOT test number</b>	624027604160
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing Slight Damage To Sidewall (5.2.3 (d) (ii))
<b>Advice</b>	Front Registration plate insecure but not likely to fall off (0.1 (a))

**MOT #16**

2022-02-07 14:30

**MOT test number**

606541059732

**Result****✗ Failed****Fail** Offside Front Tyre has ply or cords exposed 225/45R18 Clearly Ran Flat (5.2.3 (d) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Slight Damage To Sidewall (5.2.3 (d) (ii))**Fail** Headlamp levelling device inoperative O/S/F Self Level Not Attached (4.1.5 (a))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear Bush (5.3.4 (a) (i))**Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))

**MOT #15**

2022-01-26 17:51

**MOT test number**

425180254573

**Result****✗ Failed****Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Exhaust deteriorated**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** General corrosion**Advice** Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Also damaged sidewall (5.2.3 (e))**Advice** Tyre pressure monitoring light on**Fail** Offside Front Headlamp aim not tested (4.1.2 (b))**MOT #14**

2021-01-27 09:37

**MOT test number**

300298793401

**Result****✓ Passed****MOT #13**

2019-10-30 11:04

**MOT test number**

753071377413

**Result****✓ Passed****Advice** Rear brake balance

**MOT #12** 2018-10-29 12:55**MOT test number** 336356827195**Result** ✓ Passed**Advice** N/s/r brake binding on slightly**Advice** Both front tyres wearing low**Advice** Headlamps starting to tarnish**Advice** N/s/r brake disc worn/corroding**MOT #11** 2017-10-26 14:55**MOT test number** 462802233213**Result** ✓ Passed**Advice** BOTH REAR TYRES WORN OUT OF SHAPE**Advice** BOTH REAR LOWER TRANSVERSE SUSPENSION ARMS INNER AND OUTER BUSHES SPLITTING/PERISHING AND HAVE SLIGHT PLAY**MOT #10** 2017-10-25 12:06**MOT test number** 711767119835**Result** ✗ Failed**Advice** BOTH REAR TYRES WORN OUT OF SHAPE**Fail** Front brake application uneven (3.7.B.2)**Advice** FRONT BRAKE DISCS WORN/CORRODED**Fail** Offside Rear Anti-roll bar linkage fractured (2.4.G.1)**Advice** BOTH REAR LOWER TRANSVERSE SUSPENSION ARMS INNER AND OUTER BUSHES SPLITTING/PERISHING AND HAVE SLIGHT PLAY**MOT #9** 2016-11-04 12:46**MOT test number** 418719598800**Result** ✓ Passed

**MOT #8** 2015-10-19 11:08**MOT test number** 255583517403**Result** ✓ Passed**Advice** Nearside front tyre near the legal limit**MOT #7** 2014-10-31 12:41**MOT test number** 337004804399**Result** ✓ Passed**MOT #6** 2014-10-31 10:37**MOT test number** 146384004309**Result** ✗ Failed**Fail** Front Brakes imbalanced across an axle (3.7.B.5b)**Notice** Offside front tyre worn to edge**Notice** Front brake pads wearing low**MOT #5** 2013-10-17 11:04**MOT test number** 868810793204**Result** ✓ Passed**Notice** Offside & nearside rear tyres wearing out of shape**MOT #4** 2012-10-17 17:26**MOT test number** 387261092415**Result** ✓ Passed**Notice** Offside front tyre worn low



MOT #3	2012-10-17 11:06
MOT test number	596271592228
Result	✗ Failed
Fail	Brakes imbalanced across an axle (3.7.B.5b)
Fail	Offside Front position lamp(s) not working (1.1.A.3b)
Notice	Offside front tyre worn low

MOT #2	2011-11-17 08:48
MOT test number	415671821485
Result	✓ Passed

MOT #1	2011-08-01 11:53
MOT test number	129593311248
Result	✓ Passed





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-08-18
Last registration	2023-01-31
Complete history	<a href="#">See info</a>



Registration #1	2008-08-18	23 mi
Registration #2	2011-08-01	29.681 mi
Registration #3	2011-11-17	31.519 mi
Registration #4	2012-10-17	56.226 mi
Registration #5	2012-10-17	56.230 mi
Registration #6	2013-10-17	63.964 mi
Registration #7	2014-10-31	71.388 mi
Registration #8	2014-10-31	71.397 mi
Registration #9	2015-10-19	77.617 mi
Registration #10	2016-11-04	82.393 mi
Registration #11	2017-10-25	87.507 mi
Registration #12	2018-01-20	91.557 mi
Registration #13	2018-01-20	91.557 mi
Registration #14	2018-01-20	91.557 mi
Registration #15	2018-01-20	91.557 mi
Registration #16	2018-01-20	91.557 mi
Registration #17	2018-01-20	91.557 mi
Registration #18	2018-01-20	91.557 mi
Registration #19	2018-01-20	91.557 mi
Registration #20	2018-01-20	91.557 mi
Registration #21	2018-01-20	91.557 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1530 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	RF 10235445