



HONDA



report date: 2024-03-29

General information

Make	HONDA
Model	FR-V VTEC SPORT
Colour	Black
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	192 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	40.9 mpg
Consumption combined	33.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-09
Pictures	30
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #18	2022-10-20 15:58
MOT test number	328929258622
Result	✓ Passed
Next expiry date	2023-11-05

MOT #17	2022-10-19 13:14
MOT test number	586658664561
Result	✗ Failed
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))	
Advice Engine oil level low	

MOT #16	2021-11-06 14:36
MOT test number	597690590703
Result	✓ Passed
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	

MOT #15	2021-11-06 13:02
MOT test number	563128202560
Result	✗ Failed
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #14	2021-01-22 16:21
MOT test number	263339925727
Result	✓ Passed

**MOT #13** 2019-07-23 15:04**MOT test number** 918759878378**Result** ✓ Passed**MOT #12** 2019-07-13 11:42**MOT test number** 781995810879**Result** ✗ Failed

- Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #11 2018-06-30 11:55**MOT test number** 400508919741**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10 2017-07-15 07:46**MOT test number** 462214650589**Result** ✓ Passed

**MOT #9** 2016-07-11 10:00**MOT test number** 281553277561**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2015-07-01 09:53**MOT test number** 346662185188**Result** ✓ Passed**Notice** Mil light on**MOT #7** 2014-06-28 15:53**MOT test number** 229199374493**Result** ✓ Passed**MOT #6** 2013-06-27 09:56**MOT test number** 965168373169**Result** ✓ Passed**Notice** Mil light on**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2012-06-30 12:14**MOT test number** 518842982199**Result** ✓ Passed

**MOT #4** 2011-06-09 13:19**MOT test number** 997500261115**Result** ✓ Passed**MOT #3** 2011-06-09 13:19**MOT test number** 235790461153**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**MOT #2** 2010-05-07 11:15**MOT test number** 573477820117**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**MOT #1** 2009-03-06 17:32**MOT test number** 113495869006**Result** ✓ Passed



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-03-09
Last registration	2022-10-20
Complete history	See info



Registration #1	2006-03-09	16 mi
Registration #2	2009-03-06	35.788 mi
Registration #3	2010-05-07	43.962 mi
Registration #4	2011-06-09	50.425 mi
Registration #5	2012-06-30	56.641 mi
Registration #6	2013-06-27	62.237 mi
Registration #7	2014-06-28	69.363 mi
Registration #8	2015-07-01	77.707 mi
Registration #9	2016-07-11	84.258 mi
Registration #10	2017-07-15	89.890 mi
Registration #11	2018-06-20	95.377 mi
Registration #12	2019-06-20	101.377 mi
Registration #13	2020-06-20	107.377 mi
Registration #14	2021-06-20	113.377 mi
Registration #15	2022-06-20	119.377 mi
Registration #16	2023-06-20	125.377 mi
Registration #17	2024-06-20	131.377 mi
Registration #18	2025-06-20	137.377 mi
Registration #19	2026-06-20	143.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2113 mm
Height	1610 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1447 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Engine number	K20A92003809