



report date: 2024-03-29

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Black
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





## MOT history

MOT expiry date	2024-09-13
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	53
Total items failed	12

## MOT #17 2023-09-14 13:55

MOT test number 456786837211

Result ✓ Passed

Next expiry date 2024-09-13

**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

## MOT #16 2023-09-13 10:23

MOT test number 356336639617

Result ✗ Failed**Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush excessively worn (5.1.2 (b) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Rear Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15**

2022-09-07 11:30

**MOT test number**

917891792795

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin NS & OS (1.1.13 (a) (ii))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Macpherson strut mounting corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Suspension arm corroded but not seriously weakened NS & OS (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Also Small Cut (Advise Replacement) (5.2.3 (e))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Coil spring corroded NS & OS (5.3.1 (b) (i))
- Advice** Rear Slight Corrosion to Rear Components

**MOT #14**

2021-09-07 12:20

**MOT test number**

194925561246

**Result**

✓ Passed

**MOT #13**

2020-09-11 08:54

**MOT test number**

880931958249

**Result**

✓ Passed

- Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
- Advice** Vehicle muddy at time of test
- Advice** Rear Child Seat fitted not allowing full inspection of adult belt two seats
- Advice** Offside Front Track rod end slightly misaligned (2.1.3 (e))
- Advice** Offside Rear slight damage on bumper

**MOT #12** 2019-09-02 07:47**MOT test number** 705236017735**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Nearside wing mirror outer casing broken, taped up
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front Exhaust has a minor leak of exhaust gases Front flexi pipe (6.1.2 (a))

**MOT #11** 2019-08-30 09:06**MOT test number** 744081666246**Result** ✗ Failed

- Fail** Rear Registration plate inscription illegible (0.1 (b))
- Advice** Nearside Nearside wing mirror outer casing broken, taped up
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Nearside Front Side repeater not working (4.4.1 (a) (ii))
- Advice** Front Exhaust has a minor leak of exhaust gases Front flexi pipe (6.1.2 (a))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

**MOT #10** 2018-06-08 15:25**MOT test number** 499986849037**Result** ✓ Passed

- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

**MOT #9** 2018-06-05 10:04**MOT test number** 801919451712**Result** ✗ Failed

- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Rear Suspension arm pin or bush excessively worn trailing arm (5.3.4 (a) (i))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2017-06-05 15:35**MOT test number** 568309222418**Result** ✓ Passed

- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)
- Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #7** 2017-06-05 09:43**MOT test number** 664981429504**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Windscreen wiper blade insecure (8.2.2)**Advice** Rear registration plate delaminated but not likely to be misread (6.3.1d)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2016-05-20 15:26**MOT test number** 187631422013**Result** ✓ Passed**MOT #5** 2015-06-05 11:07**MOT test number** 856086855100**Result** ✓ Passed**MOT #4** 2014-06-06 08:54**MOT test number** 365037054148**Result** ✓ Passed**MOT #3** 2013-06-28 10:58**MOT test number** 269929473425**Result** ✓ Passed



MOT #2	2012-07-06 11:02
MOT test number	415388582152
Result	✓ Passed

MOT #1	2011-06-24 11:09
MOT test number	779215971187
Result	✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Advise nearside rear brake disc slightly worn/ scored
- Notice** Advise damage to all four inner wheel rims
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Advise both rear tyres worn unevenly



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>EF08LPJ</b>
Plate since	2019-03-29
Current registration	<b>EF08LPJ</b>
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-07-10
Last registration	2023-09-14
Complete history	<a href="#">See info</a>



Registration #1	2008-07-10	28 mi
Registration #2	2011-06-24	34.300 mi
Registration #3	2012-07-06	45.590 mi
Registration #4	2013-06-28	56.160 mi
Registration #5	2014-06-06	64.313 mi
Registration #6	2015-06-05	73.478 mi
Registration #7	2016-05-20	75.777 mi
Registration #8	2017-06-05	83.887 mi
Registration #9	2017-06-05	83.887 mi
Registration #10	2018-06-05	91.997 mi
Registration #11	2019-06-05	100.107 mi
Registration #12	2020-06-05	108.217 mi
Registration #13	2021-06-05	116.327 mi
Registration #14	2022-06-05	124.437 mi
Registration #15	2023-06-05	132.547 mi
Registration #16	2024-06-05	140.657 mi
Registration #17	2025-06-05	148.767 mi
Registration #18	2026-06-05	156.877 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1736 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	8R43181