



report date: 2024-03-28

General information

|                     |                       |
|---------------------|-----------------------|
| Make                | CITROEN               |
| Model               | C5 HDI VTR PLUS SCORE |
| Colour              | Black                 |
| Year of manufacture | -                     |
| Top speed           | 138 mph               |
| 0 - 60 mph          | 12.2 seconds          |
| Gearbox             | 5 speed Manual        |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 110 BHP             |
| Max. torque             | 240 Nm at 1.750 rpm |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 42.8 mpg            |
| Consumption extra urban | 61.4 mpg            |
| Consumption combined    | 53.3 mpg            |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-06-26                  |
| Pictures      | 0                           |
| Listing price | <a href="#">View report</a> |

source: cargurus.co.uk



## MOT history

|                  |   |
|------------------|---|
| MOT #14          | 2022-06-30 08:21  |
| MOT test number  | 535629607708  |
| Result           | ✓ Passed  |
| Next expiry date | 2023-07-08  |
| Advice           | Exhaust has a minor leak of exhaust gases (6.1.2 (a))   |
| Advice           | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))                |
| Advice           | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))   |
| Advice           | Oil leak, but not excessive (8.4.1 (a) (i))   |
| Advice           | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))                                |
| Minor            | Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |

|                 |  |
|-----------------|--|
| MOT #13         | 2021-07-09 14:33   |
| MOT test number | 311649237992   |
| Result          | ✓ Passed   |
| Advice          | Central Rear Oil leak, but not excessive (8.4.1 (a) (i)) |

|                 |  |
|-----------------|--|
| MOT #12         | 2021-07-09 11:52   |
| MOT test number | 426119650314   |
| Result          | ✗ Failed   |
| Fail            | Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))                        |
| Fail            | Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii)) |
| Advice          | Central Rear Oil leak, but not excessive (8.4.1 (a) (i))   |

**MOT #11**

2020-08-27 16:14

**MOT test number**

666258506707

**Result**

✓ Passed

- Advice** Under body covers fitted
- Advice** Oil leak
- Advice** Front Lower suspension arm bushes deteriorating

**MOT #10**

2020-08-26 14:10

**MOT test number**

506625739665

**Result**

✗ Failed

- Advice** Front Lower suspension arm bushes deteriorating
- Advice** Under body covers fitted
- Fail** Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt n/s & o/s (6.1.7 (g) (ii))
- Fail** Front Tyre tread depth below requirements of 1.6mm n/s & o/s (5.2.3 (e))
- Advice** Oil leak

**MOT #9**

2019-07-11 13:58

**MOT test number**

940872281735

**Result**

✓ Passed

- Advice** Offside Rear Inner side light not working
- Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Central brake light
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8**

2019-07-11 11:13

**MOT test number**

594536562762

**Result****✗ Failed****Advice**

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

**Advice**

Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail**

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice**

Central brake light

**Advice**

Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail**

Nearside Front Tyre tread depth below requirements of 1.6mm 215/60/16 (5.2.3 (e))

**Advice**

Offside Rear Inner side light not working

**MOT #7**

2018-07-13 08:18

**MOT test number**

128234300003

**Result****✓ Passed****Advice**

Offside Front day running light not working

**Advice**

Items removed from driver's view prior to test air freshner

**MOT #6**

2018-07-12 09:47

**MOT test number**

974793170342

**Result****✗ Failed****Fail**

Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Minor**

Offside Rear Registration plate lamp insecure (4.7.1 (c) (i))

**Advice**

Offside Front day running light not working

**Advice**

Items removed from driver's view prior to test air freshner

**MOT #5** 2017-06-13 09:14**MOT test number** 138721873363**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-09-14 13:52**MOT test number** 721360453212**Result** ✓ Passed**Advice** Exhaust noisy (7.1.4)**MOT #3** 2015-09-15 12:05**MOT test number** 182432581035**Result** ✓ Passed**MOT #2** 2014-09-16 10:55**MOT test number** 868039154297**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-09-12 10:56**MOT test number** 269905653287**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Wheel trims fitted**Notice** Engine covers fitted obscuring some components in the engine bay



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |              |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this CITROEN had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration |            |
| Plate since          | 2019-09-29 |
| Current registration |            |
| Plate since          | 2019-09-29 |

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 16                       |
| First mileage registration | 2010-09-24               |
| Last registration          | 2022-06-30               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2010-09-24 | 23 mi     |
| Registration #2  | 2013-09-12 | 23.176 mi |
| Registration #3  | 2014-09-16 | 26.951 mi |
| Registration #4  | 2015-09-15 | 30.750 mi |
| Registration #5  | 2016-09-14 | 35.554 mi |
| Registration #6  | 2017-06-13 | 38.129 mi |
| Registration #7  | 2018-07-12 | 50.584 mi |
| Registration #8  | 2018-07-13 | 50.896 mi |
| Registration #9  | 2019-06-20 | 51.217 mi |
| Registration #10 | 2019-06-20 | 51.217 mi |
| Registration #11 | 2019-06-20 | 51.217 mi |
| Registration #12 | 2019-06-20 | 51.217 mi |
| Registration #13 | 2019-06-20 | 51.217 mi |
| Registration #14 | 2019-06-20 | 51.217 mi |
| Registration #15 | 2019-06-20 | 51.217 mi |
| Registration #16 | 2019-06-20 | 51.217 mi |

More info >



Safety ratings

|                |                                 |
|----------------|---------------------------------|
| NCAP rating    | ★★★★★                           |
| Adult          | 81%                             |
| Children       | 77%                             |
| Pedestrian     | 32%                             |
| Safety systems | 83%                             |
| Overall rating | 71%                             |
| Video          | <a href="#">see crash video</a> |



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1853 mm |
| Height              | 1456 mm |
| Length              | 4779 mm |
| Wheel base          | 2815 mm |
| Kerb weight         | 1503 kg |
| Max. allowed weight | 2045 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 71 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 4                |
| Number of seats    | 5                |
| Number of axles    | 2                |
| Engine number      | JBBN0098245      |