



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Blue
Year of manufacture	-
Top speed	96 mph
0 - 60 mph	14.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	64 BHP
Max. torque	102 Nm at 3.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	46.3 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-26
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #15	2022-10-12 11:44
MOT test number	110379475300
Result	✓ Passed
Next expiry date	2023-10-23
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #14	2021-10-13 09:58
MOT test number	876190349744
Result	✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Oil leak, but not excessive TRANSMISSION (8.4.1 (a) (i))

MOT #13	2020-10-06 09:19
MOT test number	709507812636
Result	✓ Passed

MOT #12	2019-10-24 14:49
MOT test number	541417772015
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #11 2018-09-17 12:52

MOT test number 219042085993

Result ✓ Passed

- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Rear exhaust box corroding

MOT #10 2018-09-17 10:08

MOT test number 129287444241

Result ✗ Failed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear exhaust box corroding
- MAJOR** Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- MAJOR** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #9** 2017-09-25 12:08**MOT test number** 948748887524**Result** ✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Rear exhaust delaminated
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Advice** Front flexi slightly damaged / front clamp corroded but adequately supported

MOT #8 2017-09-22 11:49**MOT test number** 575575122409**Result** ✗ Failed

- Fail** Offside Rear Rear fog lamp not working (1.3.2b)
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)
- Advice** Rear parking (secondary) brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. pass due to nearside wheel lock (3.7.B.6b)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Front flexi slightly damaged / front clamp corroded but adequately supported
- Advice** Nearside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)
- Fail** Offside rear brake recording little or no effort (3.7.B.5a)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Rear exhaust delaminated

**MOT #7** 2016-09-24 11:03**MOT test number** 567768257979**Result** ✓ Passed**Advice** Both front top mounts rough (notchy)**MOT #6** 2015-09-19 10:24**MOT test number** 359408833854**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear exhaust box corroded**MOT #5** 2014-09-20 11:46**MOT test number** 496293564219**Result** ✓ Passed**Notice** Brake pedal anti-slip cover worn**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Advice** Nearside Rear coil spring corroded (2.4.C.1b)**MOT #4** 2013-09-27 14:39**MOT test number** 989810873241**Result** ✓ Passed

**MOT #3**

2012-09-22 11:54

MOT test number

475456862287

Result

✓ Passed

Advice Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Nail in nearside front tyre**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2**

2011-08-26 16:56

MOT test number

618418231200

Result

✓ Passed

Advice Parking brake lever has little reserve travel (3.1.6b)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #1**

2011-08-22 14:48

MOT test number

387934631259

Result

✗ Failed

Fail Front brakes release unevenly (3.7.B.4)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Fail** Steering column movement between the shaft and steering wheel (2.1.2b)**Fail** Offside Ball joint has excessive play (2.2.B.1f)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Ball joint has excessive play (2.2.B.1f)



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	RK08SXW
Plate since	2024-03-28
Current registration	RK08SXW
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-26
Last registration	2022-10-12
Complete history	See info



Registration #1	2008-03-26	22 mi
Registration #2	2011-08-22	50.630 mi
Registration #3	2011-08-26	50.635 mi
Registration #4	2012-09-22	71.000 mi
Registration #5	2013-09-27	86.913 mi
Registration #6	2014-09-20	94.113 mi
Registration #7	2015-09-19	99.182 mi
Registration #8	2016-09-24	105.258 mi
Registration #9	2017-09-22	112.071 mi
Registration #10	2018-09-22	118.071 mi
Registration #11	2019-09-22	124.071 mi
Registration #12	2020-09-22	130.071 mi
Registration #13	2021-09-22	136.071 mi
Registration #14	2022-09-22	142.071 mi
Registration #15	2023-09-22	148.071 mi
Registration #16	2024-09-22	154.071 mi
Registration #17	2025-09-22	160.071 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	4363732