



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	IX35 CRDI S
Colour	Black
Year of manufacture	2014
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	53.3 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-07-14
Pictures	2
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-07-13
Pictures	2
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-29
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	27
Total items failed	0

MOT #10	2023-07-13 09:02
MOT test number	627599874218
Result	✓ Passed
Next expiry date	2024-07-29

MOT #9	2022-07-25 15:57
MOT test number	590526032402
Result	✓ Passed

MOT #8	2022-07-25 09:55
MOT test number	719692589211
Result	✗ Failed
MAJOR Position lamp not working (4.2.1 (a) (ii))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #7	2021-07-30 12:09
MOT test number	508079520493
Result	✓ Passed

**MOT #6** 2020-12-04 12:33**MOT test number** 350027221020**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Dot 4813 (215/70r16 (5.2.3 (d) (ii))
- Advice** Parking brake lever free play / little reserve travel
- Advice** Front Brake pad(s) wearing thin Nearside and offside (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Dot 4813 (215/70r16 (5.2.3 (d) (ii))
- Advice** T.P.M.S light illuminated
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.9mm (215/70r16 (5.2.3 (e))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Front Brake disc worn, but not excessively Nearside and offside - lipped (1.1.14 (a) (i))

MOT #5 2019-11-13 12:23**MOT test number** 579062929052**Result** ✓ Passed

- Advice** Rear Tyre slightly damaged/cracking or perishing Nearside and offside dot codes 4813 (215/70r16 (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, but not excessively Nearside and offside slightly lipped (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin Nearside and offside (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, but not excessively Nearside and offside slightly lipped (1.1.14 (a) (i))
- Advice** T.P.M.S illuminated

**MOT #4**

2019-11-13 10:48

MOT test number

965021630406

Result**✗ Failed**

Advice Rear Tyre slightly damaged/cracking or perishing Nearside and offside dot codes 4813 (215/70r16 (5.2.3 (d) (ii))

MAJOR Brake lever has insufficient reserve travel (1.1.2 (a))

Advice Rear Brake disc worn, but not excessively Nearside and offside slightly lipped (1.1.14 (a) (i))

Advice Parking brake only just meets requirements (17%

DANGEROUS Rear Brake pad(s) less than 1.5 mm thick Nearside and offside (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin Nearside and offside (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively Nearside and offside slightly lipped (1.1.14 (a) (i))

Advice T.P.M.S illuminated

MOT #3

2018-11-26 10:06

MOT test number

953827129378

Result**✓ Passed**

Minor Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))

Advice Nearside rear tyre perishing on edges. 215/70r16 Dot 48/13

MOT #2

2017-12-07 10:56

MOT test number

253848510194

Result**✓ Passed****MOT #1**

2017-02-20 09:34

MOT test number

876387874592

Result**✓ Passed**

Advice Front Tyre worn close to the legal limit both sides (4.1.E.1)

Advice Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
29 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	29 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-03-01
Last registration	2023-07-13
Complete history	See info



Registration #1	2014-03-01	19 mi
Registration #2	2017-02-20	35.244 mi
Registration #3	2017-12-07	38.966 mi
Registration #4	2018-11-26	42.785 mi
Registration #5	2019-11-13	46.416 mi
Registration #6	2019-11-13	46.416 mi
Registration #7	2020-12-04	49.326 mi
Registration #8	2020-12-04	51.277 mi
Registration #9	2020-12-04	51.277 mi
Registration #10	2020-12-04	51.277 mi
Registration #11	2020-12-04	51.277 mi
Registration #12	2020-12-04	51.277 mi
Registration #13	2020-12-04	51.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1655 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDDZ240823