





report date: 2024-03-28

#### General information

Make	PEUGEOT
Model	206 SE
Colour	Silver
Year of manufacture	2004
Top speed	99 mph
0 - 60 mph	15.2 seconds
Gearbox	4 speed automatic

### Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Engine capacity	1.360 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.7 mpg
Consumption extra urban	52.3 mpg
Consumption combined	40.9 mpg
CO2 emission	165 g/km
CO2 label	G



CarCheck.co.uk page 1/16



report date: 2024-03-28

## Internet history

E	n	t	ry	1

Lifety 1	
Date	2021-09-18
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/16



report date: 2024-03-28

# MOT history

MOT expiry date	2024-09-16
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	44
Total items failed	8

MOT #23	023-09-14 10:57
MOT test number	696660915754
Result	✓ Passed
Next expiry date	2024-09-16
Advice Rear Exhaust has a minor leak of exhaust gases box (6.1.2 (a))	
Minor Front Anti-roll bar ball joint dust cover severely deteriorated both side (5.3.4 (b) (i))	

MOT #22		2022-09-10 11:50
MOT test	number	610797771595
Result		✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7)	7 (g) (i))
Advice	Gearbox mounting defective	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Rear Exhaust mounting defective (6.1.2 (a))	

MOT #21	2021-09-17 13:31
MOT test number	505386841321
Result	✓ Passed

CarCheck.co.uk page 3/16



report date: 2024-03-28

**MOT #20** 2021-08-11 15:59

**MOT test number** 869605547273

Result X Failed

**Advice** Gearbox mounting defective

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Exhaust mounting defective (6.1.2 (a))

**MAJOR** Oil leaking excessively from engine (8.4.1 (a) (i))

**Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #19** 2020-08-26 08:01

**MOT test number** 280436389559

Result 

Passed

**Advice** Exhaust mounting defective rear box rubber hanger split (6.1.2 (a))

**MOT #18** 2020-08-21 15:50

MOT test number 665606843655

**Result** X Failed

**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Exhaust mounting defective rear box rubber hanger split (6.1.2 (a))

**MOT #17** 2019-05-10 08:52

**MOT test number** 198604077217

**Result** 
✓ Passed

CarCheck.co.uk page 4/16



report date: 2024-03-28

MOT #16

MOT test number

635553789500

Result

Advice Oil leak

Advice Play in steering rack inner joint(s)

MOT test number
725732176037

Result

Advice Play in steering rack inner joint(s)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Advice Oil leak

Fail Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #14 2017-04-28 10:53

MOT test number 351199407070

Result ✓ Passed

MOT test number
939772464311

Result

Advice Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

Advice Offside Headlamp deteriorated but light output not reduced (1.7.5a)

CarCheck.co.uk page 5/16



report date: 2024-03-28

MOT test number
626606762050

Result

Advice
Lower engine mounting deteriorated, but not resulting in excessive movement (6.1.D.1a)

Advice
Offside Headlamp deteriorated but light output not reduced (1.7.5a)

Fail
Offside Front Brake hose excessively damaged (3.6.B.4d)


Advice
Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

MOT #11 2015-04-17 12:09 885317305109 **MOT** test number Result ✓ Passed **MOT #10** 2014-05-14 08:47 **MOT** test number 468734834173 Result ✓ Passed **Notice** Items removed from driver's view prior to test Notice Oil leak Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f) Notice Front brake discs pitted

CarCheck.co.uk page 6/16



report date: 2024-03-28



MOT #8		2013-05-04 11:51
MOT test	number	299464323479
Result		<b>✓</b> Passed
Advice	Offside Front Brake hose slightly damaged (3.6.B.4d)	
Notice	Front discs have slight lip	
Notice	Items removed from driver's view prior to test	
Notice	All tyres showing signs of age and cracking in tread	

CarCheck.co.uk page 7/16



report date: 2024-03-28

MOT #7	2013-05-01 09:35
MOT test number	736461623183
Result	<b>X</b> Failed
Fail Offside Headlamp aim too low (1.8)	
Advice Offside Front Brake hose slightly damaged (3.6.B.4d)	
Notice Items removed from driver's view prior to test	
Notice All tyres showing signs of age and cracking in tread	
Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3	3.1a)
Fail Exhaust system not adequately supported (7.1.1)	
Notice Front discs have slight lip	

MOT #6	2012-04-17 13:44
MOT test number	217548402452
Result	✓ Passed
MOT #5	2011-04-19 08:43
MOT test number	136039501174
Result	✓ Passed
MOT #4	2010-04-28 12:32
MOT test number	133608610127
Result	✓ Passed
MOT #3	2009-04-29 15:44
MOT test number	963349319177
Result	✓ Passed

CarCheck.co.uk page 8/16



report date: 2024-03-28

MOT #2	2008-04-14 10:57
MOT test number	424355908107
Result	<b>✓</b> Passed
MOT #1	2007-04-18 13:07
MOT test number	513158707191
Result	✓ Passed

CarCheck.co.uk page 9/16



report date: 2024-03-28

#### Tax & MOT check





**Expires:** 16 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	16 September 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 10/16



report date: 2024-03-28

#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 12/16



report date: 2024-03-28

$^{\prime}$	wn	Δr	h	ic	t٥	'n

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
************	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SILE
Plate since	
	More info >

CarCheck.co.uk page 13/16



report date: 2024-03-28

#### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

**Contact info** 

More info >

CarCheck.co.uk page 14/16



report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-04-19
Last registration	2023-09-14
Complete history	See info



Registration #1	2004-04-19	16 mi
Registration #2	2007-04-18	9.556 mi
Registration #3	2008-04-14	12.207 mi
Registration #4	2009-04-29	15.613 mi
Registration #5	2010-04-28	18.579 mi
Registration #6	2011-04-19	21.468 mi
Registration #7	2012-04-17	23.727 mi
Registration #8	2013-05-01	24.823 mi
Registration #9	2013-05-04	24.824 mi
Registration #10	2014-05-09	26.691 mi
Registration #11	2014-05-14	26.691 mi
Registration #12	2015-04-17	28.196 mi
Registration #13	2016-05-04	29.000 mi
Registration #14		77,777 46
Registration #15		71.777 66
Registration #16		77,777 46
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		0.074
Registration #22		11.777 es
Registration #23		11.777 46
-		71.777 es



report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1652 mm
Height	1426 mm
Length	3835 mm
Wheel base	2445 mm
Kerb weight	1055 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number CarCheck.co.uk	FSM34685917 page 16/16